

Motoro	bla GmbH, CSS Center Flensburg, Mobile Devices
Title:	Troubleshooting-Guide E398

# E398 DebugGuide





Repair Support Information	© Copyright 2003-2005 Motorola Inc. All Rights reserved. Motorola internal use

MOTOROLA	Version:	TSG_E398 0.9c 17.06.2005
Title: Troubleshooting-Guide E398	Page:	2 / 12

## **Table of Contents**

- 1.0 Preamble
- 2.0 Some Basic Tips
  - 2.1 Software Upgrade
  - 2.2 Visual Inspection
  - 2.3 Cross Check
  - 2.4 Solder Process
- 3.0 Top 10 Defective Parts
- 4.0 Most frequently Failure Codes and Root Causes
- 5.0 Troubleshooting
  - 5.1 Alert
  - 5.2 Audio
  - 5.3 Battery
  - 5.4 Charging
  - 5.5 Display Backlight
  - 5.6 Main Keypad
  - 5.7 Power Up (TON01)
  - 5.8 Power Up (TON03)
  - 5.9 TX

Modified	Date	Ву

Repair Support Information	© Copyright 2003-2005 Motorola Inc. All Rights reserved. Motorola internal use
----------------------------	---

MOTOROLA	Doc. No: Version: Date:	TSG_E398 0.9c 17.06.2005
Title: Troubleshooting-Guide E398	Page:	3 / 12

# 1.0 - Preamble

This Document was created to assist Analyzers, when fixing Problems on Motorola GSM Phones. All Information was collected during the Repair in the Repair Entitlement Group Flensburg.

Benair Support Information © Copyright 2003-2005 Motorola Inc. All Rights reserv	
Repair Support Information         © Copyright 2003-2005 Motorola Inc. All Rights reserv           Motorola internal use         Motorola internal use	ed.

MOTOROLA	Version:	TSG_E398 0.9c 17.06.2005
Title: Troubleshooting-Guide E398	Page:	4 / 12

## 2.0 - Some Basic Tips


- 2.1 Software upgrade
  - always use the latest Software available for the phone (Softwarebugs are excluded)
- 2.2 Visual inspection
  - check for liquid damage (water indicator)
  - check for missing, broken or unsoldered parts
  - check for mechanical damage (board twisted, tracks defect etc.)
- 2.3 Cross check
  - before beginning to replace/change parts or soldering anything try to consider the failure from all sides.
- 2.4 Solder process
  - the soldering process of lead-free products always must be done with the aid of a bottom-heater and flux for lead-free soldering
  - always cover sensitive parts with shields

Repair Support Information	© Copyright 2003-2005 Motorola Inc. All Rights reserved. Motorola internal use
----------------------------	---


MOTOROLA	Version:	TSG_E398 0.9c 17.06.2005
Title: Troubleshooting-Guide E398	Page:	5 / 12

# 3.0 - Top 10 Defective Parts

This is the Analysis of the repaired Phones in NPI-Process, related to the first repair works at all.



Repair Support Information	© Copyright 2003-2005 Motorola Inc. All Rights reserved. Motorola internal use
----------------------------	---



# 4.0 - Most frequently Failure Codes and Root Causes

ALTxx	- U900
AUDxx	- Microphone, J2000, U900, U800
BATxx	- U50
CHGxx	- J1400, FI1400, U900, J950, CR900, U900
DIMxx	- J1301, L960, D960
MKPxx	- Keyboard, J1401, J1301, U1400, U1401, S1460, SW100, SW1402, U800
TON01	- Y900, U900, Y805, U800, U700
TON03	- Y900, U900
CPRxx	- U50, U150, J40

Repair Support Information	© Copyright 2003-2005 Motorola Inc. All Rights reserved. Motorola internal use
----------------------------	---

MOTOROLA	Doc. No: Version: Date:	TSG_E398 0.9c 17.06.2005
Title: Troubleshooting-Guide E398	Page:	7 / 12

## 5.0 - Troubleshooting


# 5.1 - Alert - Customer Complaint: ALTxx

- 1.) If the Alert is not working
  - check:- Chassis Speaker Assy

- J1261

- the Components around D961
- the Components around D962
- for Dry Joints, Solder Shorts, damaged and skewed Parts
- replace missing or damaged Components
- 2.) If the Alert is still not working

replace: - U900



Repair Support Information	© Copyright 2003-2005 Motorola Inc. All Rights reserved. Motorola internal use
----------------------------	---

MOTOROLA	Version:	TSG_E398 0.9c 17.06.2005
Title: Troubleshooting-Guide E398	Page:	8 / 12

# 5.2 - Audio - Customer Complaint: AUDxx


- 1.) If Audio is not working
  - check:- the Microphone
    - J2000
    - the Components around the Microphone
    - the Components around TP1200
    - the Components around TP1201
    - the Components around U900

#### If Audio is still not working check at TP1200 and TP1201 ≈ 1,4V DC

replace:

- U900 (if not effective)

- U800



# 5.3 - Battery - Customer Complaint: BATxx

1.) If the Battery and/or the PA-Area is getting hot replace: - U50

MOTOROLA	Version:	TSG_E398 0.9c 17.06.2005
Title: Troubleshooting-Guide E398	Page:	9 / 12

## 5.4 - Charging - Customer Complaint:CHGxx

1.) If charging is not possible check:- J1400

- FL1400

- U900 - J950


- CR900

- for Dry Joints, Solder Shorts, damaged and skewed Parts

- replace missing or damaged Components

2.) If charging is still not possible check "BATT FDBK" at CR900 (if not effective)

> - U900 replace:



	right 2003-2005 Motorola Inc. All Rights reserved. a internal use
--	--


MOTOROLA	Version:	TSG_E398 0.9c 17.06.2005
Title: Troubleshooting-Guide E398	Page:	10 / 12

## 5.5 Display Backlight - Customer Complaint: DIMxx

- 1.) If the Display Backlight is not working check:- J1301
- for Dry Joints, Solder Shorts, damaged and skewed Parts
- replace missing or damaged Components
- 2.) If the Display Backlight is still not working check the "BACKLIGHT 5V" at C1454

replace: -

L960 (if not effective)
D960



Repair Support Information	© Copyright 2003-2005 Motorola Inc. All Rights reserved. Motorola internal use
----------------------------	---

MOTOROLA Motorola GmbH, CSS Center Flensb	Version: Date:	TSG_E398 0.9c 17.06.2005
Title: Troubleshooting-Guide E398	Page:	11 / 12

### 5.6 - Main Keypad - Customer Complaint: MKPxx

1.) If the Main Keypad is not working

check:- the Keyboard

- J1401 - J1301 - U1400 - U1401 - S1460 - SW1400

- SW1402

- for Dry Joints, Solder Shorts, damaged and skewed Parts

- replace missing or damaged Components

2.) If the Main Keypad is still not working

- replace: U1400 (if not effective)
  - U1401 (if not effective)
  - U800

## 5.7 - Power Up - Customer Complaint: TON01

1.) If the PCB doesn't start up check the 32kHz at Y900

replace: - Y900 (if not effective) - U900

check the 26MHz at Y805

replace: - Y805 (if not effective) - U800

- 2.) If the PCB starts Up in Flashmode
  - replace: U700 (current drain ~ 1,5mA)
- 3.) If the PCB doesn't start up

check VBOOST (5,6V) at L922, L921, CR921 and U900 replace if suspect

check VBUCK (1,9V) at L920, CR920, R920, C927 and U900 replace if suspect

MOTOROLA	Version:	TSG_E398 0.9c 17.06.2005
Title: Troubleshooting-Guide E398	Page:	12 / 12

## 5.8 - Power Up - Customer Complaint: TON03

1.) If the PCB switches itself off in Standby check 32kHz at Y900

replace: - Y900 (if not effective) - U900

# 5.9 - TX - Customer Complaint: CPRxx

- 1.) If TX is not working
  - check:- U50
    - U150
    - J40
    - the Components around U50
- for Dry Joints, Solder Shorts, damaged and skewed Parts
- replace missing or damaged Components
- 2.) If TX is still not working
  - check TX-Output at A1, L1, C7, J40, C45 and L47 check TX-Input at R80 (GSM) and R81 (DCS)
  - replace: U50 (if not effective) - U150

Repair Support Information	© Copyright 2003-2005 Motorola Inc. All Rights reserved. Motorola internal use
----------------------------	---