

No Turn on Debug Guide

Objective

This guide is meant to be a step by step troubleshooting procedure for narrowing down the root cause of no turn on failures.

Instructions

Start on the Main Debug Flow page and follow the procedure. There are links to other sections of the document that contain helpful information or further debug steps. There are also back arrows on some pages meant to return to the original debug steps.

Equipment

This guide assumes access to the following equipment:

Multimeter with probes capable of probing 0201 components

-Oscilloscope

-Battery eliminator

-Power supply with current measuring capability

-Factory cable connected to power supply with current measuring capability

-PC with ability to flash software using fastboot and qflash tools

Revisions

This document will be updated and improved as new failures are analyzed. Please send feedback to Rick Jakubowski at w36108@motorola.com.

Revision History


-Document created 6/3/2013, Rick Jakubowski

-Added off/on current and stuck flash mode debug guides, 6/14/2013, Rick Jakubowski/Sanjay Patel



-Added debug steps for units that flash bootloader successfully but don't power up, 7/10/2013, Rick Jakubowski

-Fixed debug order of turn on sequence, 7/11/2013, Rick Jakubowski

Main Debug Flow





No Power On Flow





The following lists nets to probe and their expected voltage. Measure in the following order. If a voltage is more than 100mV different, there is a failure on that node. Check all parts on the node for process damage, xray IC balls, and take resistance measurement to look for a short. Also take diode drop measurement with multimeter.

Power up Sequence Flow



High Off Current Debug Procedure

The debug technique for finding the defect causing high off current involves measuring the voltage drop between two points using a multimeter. The copper routing of the pcb trace has a resistance which will cause a voltage drop between two points along the same trace according to $V = IR$ where I is the current going through the trace and R is the resistance of the trace between the two points being probed. If the current is in the μA range then a precision instrument will be needed that can measure voltage of less than $10\mu V$. If the current is in the several mA range then a less precise instrument can be used. There is a graphic showing the B_PLUS and BATT_PLUS routing of the board. Pick two points to measure while a battery is attached and the high off current is being drawn from the battery. Compare to a good board to isolate the location of the extra current.





The following lists nets to probe for resistance. Measure resistance from net to ground plane and compare to normal board. Note extremely low resistance. Also measure diode drop and compare to normal board.



Power up Sequence Flow





Flash Failure Flow



Enumeration failure flow



Probe point locations



Flash failure output and current profiles

Motorola qflash Utility version 1.3
COMPORT :COM12
RAMLOADER :MPRG8960.hex
type is 0x21
7 mbn file name singleimage.bin type 33
verbose mode on
Motorola qflash dll version 1.6
RAMLOADER VERSION: PBL_DloadVER2.0

DEVICE INFORMATION:



Version : 0x8
Min Version : 0x1
Max Write Size: 0x600
Model : 0x90
Device Size : 0
Description : Intel 28F400BX-TL or Intel 28F400BV-TL

Using passed in packet size, changing from 0x600 -> 0x600
EXTENDED_LINEAR_ADDRESS_REC @ 0x2a000000

Write 65536 bytes @ 0x2a000000
100EXTENDED_LINEAR_ADDRESS_REC @ 0x2a010000

Write 11840 bytes @ 0x2a010000
100START_LINEAR_ADDRESS_REC @ 0x2a000000

EOF_REC
Sleeping for 3s
Write, GetLastError:31, hdlc_finalize_packet: failed to write buffer
sd_hello() - Failed to send frame
Write, GetLastError:31, hdlc_finalize_packet: failed to write buffer
sd_hello() - Failed to send frame
Write, GetLastError:31, hdlc_finalize_packet: failed to write buffer
sd_hello() - Failed to send frame
Write, GetLastError:31, hdlc_finalize_packet: failed to write buffer
sd_hello() - Failed to send frame
Write, GetLastError:31, hdlc_finalize_packet: failed to write buffer
sd_hello() - Failed to send frame
Write, GetLastError:31, hdlc_finalize_packet: failed to write buffer
sd_send_nop : failed to send frame
Write, GetLastError:31, hdlc_finalize_packet: failed to write buffer
sd_send_nop : failed to send frame
failed to establish handshake with device, after 6 retries, sync error code -1



Motorola qflash Utility version 1.3
COMPORT :COM12
RAMLOADER :MPRG8960.hex
type is 0x21
7 mbn file name singleimage.bin type 33
verbose mode on
Motorola qflash dll version 1.6
RAMLOADER VERSION: PBL_DloadVER2.0

DEVICE INFORMATION:

Version : 0x8
Min Version : 0x1
Max Write Size: 0x600
Model : 0x90
Device Size : 0
Description : Intel 28F400BX-TL or Intel 28F400BV-TL

Using passed in packet size, changing from 0x600 -> 0x600
EXTENDED_LINEAR_ADDRESS_REC @ 0x2a000000

Write 65536 bytes @ 0x2a000000
100EXTENDED_LINEAR_ADDRESS_REC @ 0x2a010000



Write 11840 bytes @ 0x2a010000
100START_LINEAR_ADDRESS_REC @ 0x2a000000
EOF_REC
Sleeping for 3s


RAM DOWNLOADER INFORMATION

cmd : 0x2
description : QCOM fast download protocol targ
version_number : 0x7
compatible_version: 0x2
max_block_size : 0x400
flash_base_address: 0x0
flash_id_len : 0x4
flash id : eMMC
window_size : 0x1e
number_of_sectors : 0x80

sd_send_security_mode: secutiry mode 0x0

ReadFile() failed, GetLastError: 31
No data read from USB. This may not be an error. Trying again...
ReadFile() failed, GetLastError: 2
No data read from USB. This may not be an error. Trying again...
ReadFile() failed, GetLastError: 2
No data read from USB. This may not be an error. Trying again...
ReadFile() failed, GetLastError: 2
No data read from USB. This may not be an error. Trying again...
ReadFile() failed, GetLastError: 2
No data read from USB. This may not be an error. Trying again...
ReadFile() failed, GetLastError: 2
No data read from USB. This may not be an error. Trying again...
ReadFile() failed, GetLastError: 2
Still no data, giving up!
sd_send_security_mode: failed to read
failed to set security mode





Motorola qflash Utility version 1.3
 COMPORT :COM11
 RAMLOADER :MPRG8960.hex
 type is 0x21
 7 mbn file name singleimage.bin type 33
 verbose mode on
 Motorola qflash dll version 1.6
 RAMLOADER VERSION: PBL_DloadVER2.0

 DEVICE INFORMATION:

Version : 0x8
 Min Version : 0x1
 Max Write Size: 0x600
 Model : 0x90
 Device Size : 0
 Description : Intel 28F400BX-TL or Intel 28F400BV-TL

Using passed in packet size, changing from 0x600 -> 0x600
 EXTENDED_LINEAR_ADDRESS_REC @ 0x2a000000

Write 65536 bytes @ 0x2a000000
 100EXTENDED_LINEAR_ADDRESS_REC @ 0x2a010000


Write 11840 bytes @ 0x2a010000
 100START_LINEAR_ADDRESS_REC @ 0x2a000000
 EOF_REC
 Sleeping for 3s



 RAM DOWNLOADER INFORMATION



cmd : 0x2
 description : QCOM fast download protocol targ
 version_number : 0x7
 compatible_version: 0x2
 max_block_size : 0x400
 flash_base_address: 0x0
 flash_id_len : 0x4
 flash id : eMMC
 window_size : 0x1e
 number_of_sectors : 0x80

sdl_send_security_mode: security mode 0x0
 Flashing singleimage.bin 1953280 bytes into device
 Keeping the first packet (1024 bytes) as hostage
 Will release it if all is flashed well
 26No data read from USB. This may not be an error. Trying again...
 No data read from USB. This may not be an error. Trying again...
 No data read from USB. This may not be an error. Trying again...
 No data read from USB. This may not be an error. Trying again...
 No data read from USB. This may not be an error. Trying again...
 No data read from USB. This may not be an error. Trying again...
 Still no data, giving up!
 sdl_stream_write: failed to read response, bytes read 0
 flash_multi_bin_image - fatal error sdl_stream_write failed

warning: read size exceeded expected expected length, possible command failure
 data received:
 0x7e0e577269746520756e7375636365737366756c2073696e63652072657456616c20213d2041434b0a29177e7e0d070000005772697
 46520756e7375636365737366756c2073696e63652072657456616c20213d2041434bfd9d7e7
 e16cf857e
 sdl_close_multi_image: response packet is wrong
 Error happened during flashing binary, error code -92







SH2000

U2000

VREG_S4

VREG_X0

VREG_L6

VREG_L4

VREG_L7

VREG_L5

VREG_L3


VREG_L1

VREG_L24


VREG_L25



VREG_S1




VREG_S3




B PLUS Routing











SH1000





BOARD HW REVISION (P3/P2C)
R1131 - 0 OHM
R1127 - 7.5K OHM
R1129 - DNP
C1130 - 0.1 uF

CUSTOMER DEPENDENT:
R1132, R1128, R1130, C1131



7327





VREG L5 Routing





VREG L3 Routing




VREG L7 Routing




VREG L6 Routing








VREG L4 Routing





VREG L1 Routing






VREG L25 Routing









VREG S4 Routing



VREG S3 Routing



VREG L24 Routing



VREG S1 Routing

