



Moto G (3rd Generation) TROUBLESHOOTING GUIDE



MOTOROLA CONFIDENTIAL

Moto G (3rd Generation)
TROUBLESHOOTING GUIDE



TABLE OF CONTENTS

1. Snapshots of Antennas	3
2. Snapshots of Main Board	12
3. LTE/WCDMA/CDMA/GSM Troubleshooting	16
4. GPS Troubleshooting	155
5. WLAN / BT / WiFi Troubleshooting	158
6. FM Troubleshooting.....	173
7. DTV Troubleshooting	180
8. Power Up Failure Troubleshooting	184
9. Charging Troubleshooting	190
10. LED / Vibrator / uSIM / microSD Troubleshooting	194
11. Sensors Troubleshooting	206
12. Touch Troubleshooting	218
13. Display Troubleshooting	223
14. Camera Troubleshooting	230
15. Audio Troubleshooting	247
16. Headset Jack Troubleshooting	264





SNAPSHOTS OF ANTENNAS



MOTOROLA CONFIDENTIAL


Moto G (3rd Generation)
TROUBLESHOOTING GUIDE

ANTENNA AND ANTENNA FEED LOCATIONS



Antenna:
BT/WiFi/GPS

Antenna: Main 1



Callisto Antenna

Antenna: Diversity



MOTOROLA CONFIDENTIAL


Moto G (3rd Generation)
TROUBLESHOOTING GUIDE



MAIN ANTENNA (LTE/WCDMA/CDMA/GSM) MATCHING CIRCUIT


MAIN ANTENNA - 1
BOTTOM LEFT MAIN ANTENNA
850/900/1900/2100+QUAD-GSM

NA/VZW/Sprint/Latam/APAC SKUs



MAIN ANTENNA - 1
BOTTOM LEFT MAIN ANTENNA
850/900/1900/2100+QUAD-GSM


EU/China SKUs



MOTOROLA CONFIDENTIAL

Moto G (3rd Generation)
TROUBLESHOOTING GUIDE

LTE ANTENNA MATCHING CIRCUIT




NA/VZW/Sprint/Latam/APAC SKUs



MOTOROLA CONFIDENTIAL

Moto G (3rd Generation)
TROUBLESHOOTING GUIDE

LTE ANTENNA MATCHING CIRCUIT



EU/China SKUs




MOTOROLA CONFIDENTIAL

Moto G (3rd Generation)
TROUBLESHOOTING GUIDE



DIVERSITY ANTENNA (LTE/WCDMA/CDMA) MATCHING CIRCUIT



NA/VZW/Sprint/Latam/APAC SKUs




MOTOROLA CONFIDENTIAL

Moto G (3rd Generation)
TROUBLESHOOTING GUIDE



DIVERSITY ANTENNA (LTE/WCDMA/CDMA) MATCHING CIRCUIT




EU/China SKUs



MOTOROLA CONFIDENTIAL

Moto G (3rd Generation)
TROUBLESHOOTING GUIDE

GPS/WIFI/BT MATCHING CIRCUIT



All SKUs




MOTOROLA CONFIDENTIAL

Moto G (3rd Generation)
TROUBLESHOOTING GUIDE



FM MATCHING CIRCUIT

REF : 4900-4949



MOTOROLA CONFIDENTIAL

Moto G (3rd Generation)
TROUBLESHOOTING GUIDE



SNAPSHOTS OF MAIN BOARD




MOTOROLA CONFIDENTIAL

Moto G (3rd Generation)
TROUBLESHOOTING GUIDE


Snapshots of Main PCB / Daughter Board – Top and Bottom




Top Side
(Battery side)




Bottom Side
(Display side)



Daughter Board
(Top Side)




Daughter Board
(Bottom Side)





Main Board – Top Placement




MOTOROLA CONFIDENTIAL

Moto G (3rd Generation)
TROUBLESHOOTING GUIDE



Main Board – Bottom Placement



MOTOROLA CONFIDENTIAL

Moto G (3rd Generation)
TROUBLESHOOTING GUIDE



LTE / WCDMA / CDMA / GSM TROUBLESHOOTING




MOTOROLA CONFIDENTIAL

Moto G (3rd Generation)
TROUBLESHOOTING GUIDE



Master Block Diagram




MOTOROLA CONFIDENTIAL

Moto G (3rd Generation)
TROUBLESHOOTING GUIDE




North America SKU Block Diagram




MOTOROLA CONFIDENTIAL

Moto G (3rd Generation)
TROUBLESHOOTING GUIDE



VZW SKU Block Diagram




MOTOROLA CONFIDENTIAL

Moto G (3rd Generation)
TROUBLESHOOTING GUIDE




Sprint/Boost/USC SKU Block Diagram



MOTOROLA CONFIDENTIAL


Moto G (3rd Generation)
TROUBLESHOOTING GUIDE

EMEA SKU Block Diagram





LATAM SKU Block Diagram




MOTOROLA CONFIDENTIAL


Moto G (3rd Generation)
TROUBLESHOOTING GUIDE



APAC SKU Block Diagram



China CDMA SKU Block Diagram




MOTOROLA CONFIDENTIAL

Moto G (3rd Generation)
TROUBLESHOOTING GUIDE



LTE/WCDMA/CDMA/GSM RADIO CHECK






WCDMA B1 Tx and Rx




MOTOROLA CONFIDENTIAL

Moto G (3rd Generation)
TROUBLESHOOTING GUIDE


LTE/WCDMA B1 TX Check Chart – No TX




LTE/WCDMA B1 TX Check Chart – Low TX




LTE/WCDMA B1 RX Check Chart (LATAM and NA variants)




LTE/WCDMA B1 RX Check Chart (APAC, EU, and China variants)



B1 TRX Circuits (PA + DPX + SP10T)



B1 TRX Circuits (WTR + PA + DPX + SP10T) Layout



MOTOROLA CONFIDENTIAL

Moto G (3rd Generation)
TROUBLESHOOTING GUIDE




LTE B2,B25/WCDMA B2/CDMA BC1 Tx and Rx




MOTOROLA CONFIDENTIAL

Moto G (3rd Generation)
TROUBLESHOOTING GUIDE


LTE B2,B25/WCDMA B2/BC1 TX Check Chart – No TX




LTE B2,B25/WCDMA B2/BC1 TX Check Chart – Low TX



LTE B2,B25/WCDMA B2/BC1 RX Check Chart




B2/B25/BC1 TRX Circuits (PA + DPX + SP10T)



MOTOROLA CONFIDENTIAL

Moto G (3rd Generation)
TROUBLESHOOTING GUIDE

B2/B25/BC1 TRX Circuits (WTR + PA + DPX + SP10T) Layout



MOTOROLA CONFIDENTIAL

Moto G (3rd Generation)
TROUBLESHOOTING GUIDE



LTE/WCDMA B3/B4 Tx and Rx




MOTOROLA CONFIDENTIAL

Moto G (3rd Generation)
TROUBLESHOOTING GUIDE




LTE B3 TX Check Chart – No TX (EU/APAC/China SKU)






LTE B3 TX Check Chart – Low TX (EU/APAC/China SKU)







LTE B3 RX Check Chart (EU/APAC/China SKU)




LTE B3 TRX CIRCUITS (PA + DPX + SP10T + SP2T)





LTE B3 TRX Circuits (WTR + PA + DPX + SP10T + SP2T) Layout




MOTOROLA CONFIDENTIAL


Moto G (3rd Generation)
TROUBLESHOOTING GUIDE




LTE B4 TX Check Chart – No TX



LTE B4/WCDMA B4 TX Check Chart – No TX(LATAM/NA/SPR/VZW SKU)




LTE B4/WCDMA B4 RX Check Chart (LATAM and NA SKUs)








LTE B4/WCDMA B4 RX Check Chart (SPR/VZW SKUs)



LTE B4 WCDMA B4 TRX CIRCUITS (PA + DPX + SP10T)



B4 TRX Circuits (WTR + PA + DPX + SP10T) Layout







LTE/WCDMA B5/B26 / CDMA BC0/10 Tx and Rx




LTE B5/B26 WCDMA B5, CDMA BC0/BC10 TX Check Chart – No TX (NA/SPR/VZW/LATAM/APAC SKU)




LTE B5/B26 WCDMA B5, CDMA BC0/BC10 TX Check Chart – No TX



LTE B5/B26 WCDMA B5, CDMA BC0/BC10 RX Check Chart (NA/SPR/VZW/LATAM/APAC SKU)




LTE B5/B26 WCDMA B5, CDMA BC0/BC10 TRX CIRCUITS (PA+DPX +SP10T)



MOTOROLA CONFIDENTIAL

Moto G (3rd Generation)
TROUBLESHOOTING GUIDE

LTE B5/B26 WCDMA B5, CDMA BC0/BC10 TRX Circuits (WTR + PA + DPX + SP10T) Layout



MOTOROLA CONFIDENTIAL

Moto G (3rd Generation)
TROUBLESHOOTING GUIDE



LTE B20, WCDMA B8 Tx and Rx




MOTOROLA CONFIDENTIAL


Moto G (3rd Generation)
TROUBLESHOOTING GUIDE




LTE B20 TX Check Chart – No TX (EU SKU)



LTE B20 TX Check Chart – Low TX




LTE B20 RX Check Chart (EU SKU)



LTE B20 TRX Circuits



Output match & Switch for WTR4905 drive out




MOTOROLA CONFIDENTIAL

Moto G (3rd Generation)
TROUBLESHOOTING GUIDE

LTE B20 TRX Circuits




Input match for MMMB PA



LTE B20 TRX Circuits




Output match for MMMB PA



LTE B20 TRX Circuits




Matching for Duplexer TX Port





LTE B20 TRX Circuits


Matching for Duplexer ANT, RX ports and WTR input matching




LTE B20 TRX Circuits



Diplexer



Coupler and RF connector




LTE B20 TRX Circuits Layout






WCDMA B8 TX Check Chart – No TX(EU/LATAM/APAC SKU)




WCDMA B8 TX Check Chart – No TX






WCDMA B8 RX Check Chart (EU/LATAM/APAC SKU)






WCDMA B8 TRX CIRCUITS (PA + DPX + SP10T)





WCDMA B8 TRX Circuits (WTR + PA + DPX + SP10T) Layout




MOTOROLA CONFIDENTIAL

Moto G (3rd Generation)
TROUBLESHOOTING GUIDE




LTE B7 TX Check Chart – No TX(NA/EU SKU)






LTE B7 TX Check Chart – Low TX(NA/EU SKU)







LTE B7 TX Check Chart – No TX(LATAM SKU)




LTE B7 TX Check Chart – Low TX(LATAM SKU)




LTE B7 TX Check Chart – No TX(APAC SKU)




LTE B7 TX Check Chart – Low TX(APAC SKU)



LTE B7 RX Check Chart(NA/EU SKU)




LTE B7 RX Check Chart(LATAM/APAC SKU)





LTE B7 TRX CIRCUITS NA/EU SKU


Please check BOM for the correct values, components here are representational





LTE B7 TRX CIRCUITS LATAM SKU


Please check BOM for the correct values, components here are representational





LTE B7 TRX CIRCUITS APAC SKU

Please check BOM for the correct values, components here are representational



LTE B7 TRX Circuits – NA/EU Layout



LTE B7 TRX Circuits – LATAM Layout



MOTOROLA CONFIDENTIAL

(3rd Generation)
TROUBLESHOOTING GUIDE

LTE B7 TRX Circuits – APAC Layout



MOTOROLA CONFIDENTIAL



LTE B12/B17 Tx and Rx




MOTOROLA CONFIDENTIAL


Moto G (3rd Generation)
TROUBLESHOOTING GUIDE



LTE B12/17 TX Check Chart – No TX




LTE B12/17 TX Check Chart – Low TX






LTE B12/17 RX Check Chart



B12/17 TRX Circuits (PA + DPX + SP4T or Diplexer)



MOTOROLA CONFIDENTIAL

Moto G (3rd Generation)
TROUBLESHOOTING GUIDE



B12/17 TRX Circuits (WTR + PA + DPX + SP4T or Diplexer) Layout






LTE B13 Tx and Rx




MOTOROLA CONFIDENTIAL

Moto G (3rd Generation)
TROUBLESHOOTING GUIDE

LTE B13 TX Check Chart – No TX




LTE B13 TX Check Chart – Low TX






LTE B13 RX Check Chart




B13 TRX Circuits (PA + DPX +LPF)



MOTOROLA CONFIDENTIAL

Moto G (3rd Generation)
TROUBLESHOOTING GUIDE

B13 TRX Circuits (WTR + PA + DPX + LPF) Layout



MOTOROLA CONFIDENTIAL

Moto G (3rd Generation)
TROUBLESHOOTING GUIDE




LTE B28A/B Tx and Rx




MOTOROLA CONFIDENTIAL

Moto G (3rd Generation)
TROUBLESHOOTING GUIDE


LTE B28A/B TX Check Chart – No TX



LTE B28A/B TX Check Chart – Low TX




LTE B28A/B RX Check Chart






LTE B28A/B TRX Circuits (PA + DPXs + SP2Ts+SP4T)



B28A/B TRX Circuits (WTR + PA + DPXs + SP2Ts+SP4T) Layout






TDD/TD-SCDMA B34/39 Tx and Rx



MOTOROLA CONFIDENTIAL


Moto G (3rd Generation)
TROUBLESHOOTING GUIDE

LTE/TD-SCDMA B34/39 TX Check Chart – No Tx







LTE/TD-SCDMA B34/39 TX Check Chart – Low Tx




LTE/TD-SCDMA B34 RX Check Chart



LTE/TD-SCDMA B39 RX Check Chart



LTE/TD-SCDMA B34/39 TX CIRCUITS (PA + FILTER + SP10T)




MOTOROLA CONFIDENTIAL

Moto G (3rd Generation)
TROUBLESHOOTING GUIDE

LTE/TD-SCDMA B34/39 RX CIRCUITS




RX Filter



MOTOROLA CONFIDENTIAL

Moto G (3rd Generation)
TROUBLESHOOTING GUIDE

B34/39 TRX Circuits (WTR + PA + SP4T + SP2T) Layout



MOTOROLA CONFIDENTIAL

Moto G (3rd Generation)
TROUBLESHOOTING GUIDE



TDD LTE B40 Tx and Rx




MOTOROLA CONFIDENTIAL

Moto G (3rd Generation)
TROUBLESHOOTING GUIDE




LTE B40 TX Check Chart – No TX






LTE B40 TX Check Chart – Low TX







LTE B40 RX Check Chart



B40 TRX Circuits (PA + BPF+ SP4T+SP2T)



B40 TRX Circuits (WTR + PA + SP4T + SP2T) Layout



MOTOROLA CONFIDENTIAL

Moto G (3rd Generation)
TROUBLESHOOTING GUIDE




TDD LTE B41 Tx and Rx




MOTOROLA CONFIDENTIAL

Moto G (3rd Generation)
TROUBLESHOOTING GUIDE


LTE B41 TX Check Chart – No TX




LTE B41 TX Check Chart – Low TX




LTE B41 RX Check Chart



B41 TRX Circuits (PA + SAW FILTER + SP4T)




B41 TRX Circuits (WTR + PA + SAW FILTER + SP4T) Layout



MOTOROLA CONFIDENTIAL

Moto G (3rd Generation)
TROUBLESHOOTING GUIDE


Diversity Rx



MOTOROLA CONFIDENTIAL

Moto G (3rd Generation)
 TROUBLESHOOTING GUIDE

Diversity Rx




MOTOROLA CONFIDENTIAL

Moto G (3rd Generation)
TROUBLESHOOTING GUIDE




MIMO/Diversity RX Check Chart






XO Supply Circuit






WFR4905 Voltage Supply Circuits



SP10T



MOTOROLA CONFIDENTIAL

Moto G (3rd Generation)
TROUBLESHOOTING GUIDE

High Bands - B7, B40, B41




NA/EMEA SKU – B7

Sprint SKU – B41

Latam SKU – B7

APAC SKU – B7 and B40






Mid Bands - B1, B2/25, B3, B4, B34, B39

NA/ZW/Sprint SKU – B2/B25, B4


EMEA/APAC SKU – B1, B3

China SKU – B3, B39








Rx Div B1/B4 Check Chart (All SKUs)



Rx Div B1/B4: (RF port {DNP in production and R137 placed} & SP10)




Rx Div B1/B4: Match Comp & SAW filter.



MOTOROLA CONFIDENTIAL

Moto G (3rd Generation)
TROUBLESHOOTING GUIDE

Rx Div B1/B4 layout.






Low Bands - B5/26, B8, B12/17, B13, B20, B28


NASKU – B5, B12/17
VZW SKU – B13, BC0,
Sprint SKU – B5/26, B12/17
EMEA SKU - B20,B8
APAC SKU – B5, B28,B8

ANT_DIV





Diversity Circuit Layout



MOTOROLA CONFIDENTIAL

Moto G (3rd Generation)
TROUBLESHOOTING GUIDE



GSM Quad Band Rx




MOTOROLA CONFIDENTIAL


Moto G (3rd Generation)
TROUBLESHOOTING GUIDE



GSM Radio Check




GSM850 Receiver Check Chart






GSM850 Receiver Circuitry



GSM850 Receiver Layout



EMEA
NA/VZW/Sprint/Latam/APAC




MOTOROLA CONFIDENTIAL


Moto G (3rd Generation)
TROUBLESHOOTING GUIDE



GSM900 Receiver Check Chart




GSM900 Receiver Circuitry




NA/VZW/Sprint

EMEA/Latam/
APAC




GSM900 Receiver Layout




MOTOROLA CONFIDENTIAL

Moto G (3rd Generation)
TROUBLESHOOTING GUIDE

GSM1800 Receiver Check Chart




GSM1800 Receiver Circuitry




MOTOROLA CONFIDENTIAL

TROUBLESHOOTING GUIDE

GSM1900 Receiver Check Chart



GSM1900 Receiver Circuitry



MOTOROLA CONFIDENTIAL

TROUBLESHOOTING GUIDE



GSM Quad Band Tx




MOTOROLA CONFIDENTIAL

Moto G (3rd Generation)
TROUBLESHOOTING GUIDE




GSM Quad Band Tx Check Chart





GSM Quad Band Tx Circuitry




MOTOROLA CONFIDENTIAL

Moto G (3rd Generation)
TROUBLESHOOTING GUIDE



GSM Quad Band Tx Circuitry



GSM LB Tx
GSM HB Tx
Common



MOTOROLA CONFIDENTIAL

Moto G (3rd Generation)
TROUBLESHOOTING GUIDE




GPS TROUBLESHOOTING




MOTOROLA CONFIDENTIAL

Moto G (3rd Generation)
TROUBLESHOOTING GUIDE

GPS Troubleshoot Flow Chart



GPS Front End Block



MOTOROLA CONFIDENTIAL

Moto G (3rd Generation)
TROUBLESHOOTING GUIDE



WLAN / BT / WiFi TROUBLESHOOTING



MOTOROLA CONFIDENTIAL

Moto G (3rd Generation)
TROUBLESHOOTING GUIDE



Bluetooth/WiFi Power-On Failure

WLAN/BT power-on failure Symptoms:

WLAN DL test firmware test commands fail
Bluetooth power-on test commands fail





Step 1 for BT/Wi-Fi Power-On Failure

- Check if the other functionality fails as well, e.g. check WLAN “power on” if Bluetooth can not be powered on. Check Bluetooth “power on” if WLAN can not be powered on.
- Both WLAN and Bluetooth share the same IC and most of the circuit, so if one of the BT/Wi-Fi fails, the other should fail as well. If only one of them fails, it is highly likely that it is not a hardware problem and it could just that the BT/Wi-Fi is turned on through the UI already and the test commands can not turn it on again.






Step 2 for BT/Wi-Fi Power-On Failure

If both BT and WLAN fails, it is highly indicative of a hardware failure.


Location of the Bluetooth and WLAN circuit (Shown on the next few pages)

Check for any visible damage around the BT/WLAN antenna/IC area.


BT/Wi-Fi Antenna Schematic



RF & 19.2MHz TCXO Input Schematic




Power Supply Schematic



MOTOROLA CONFIDENTIAL

Moto G (3rd Generation)
TROUBLESHOOTING GUIDE

Part Placement



MOTOROLA CONFIDENTIAL

Moto G (3rd Generation)
TROUBLESHOOTING GUIDE



Part placement - 2



RF Components



VREG_L9_3P3 Components



VREG_S3_1P3 Components



19.2MHz TCXO Components



C4702



VREG_L7_1P8 Component



VREG_L5_1P8 Component



MOTOROLA CONFIDENTIAL

Moto G (3rd Generation)
TROUBLESHOOTING GUIDE

Step 3 for BT/Wi-Fi Power-On Failure



If no visible damage can be seen, open up the shield and check for any visible damage on the IC and components. Look for misplaced or damaged components.





Debugging BT / WLAN Power-Up Failure

- Check clock supplies
 - 19.2MHz Clock: NET TCXO_IN check at component C4600
- Check DC Voltages
 - Typical DC voltages in WCN3620 (U4600) area
 - C4711, C4714, E4710, C4715, C4716, C4717, C4718, C4719 and C4720 should be 1.3V
 - R4703 and C4704 should be 3.3V
 - C4700 and C4701 should be 1.8V





Debugging BT / WLAN Power-up Failure

- Check connections WCN3620 and MSM8226:
 - WLAN: no probing point – use x-ray or other means to make sure following is soldered properly
 - Pins 54, 59, 47 and 53 of U4600 (these are connection points of IQ lines)
 - Pins 55, 26, and 48 of U4600 (these are connection points of DATA lines)
 - Bluetooth: no probing point – use x-ray or other means to make sure following is soldered properly
 - Pins 18, 33 and 28 of U4600 (these are connection points of control, SSBI and data lines)





Debugging BT/WLAN Low TX Power

- Probe and measure the output power at the antenna contact area or at R060 and see in a spectrum analyzer if you see if the phone is transmitting any power
- Please measure the output power in test mode using the **Labview test SW**





Bluetooth/WiFi TX/RX RF Failure


- BT/Wi-Fi TX/RX RF failure
 - Symptoms:
 - Wi-Fi Radiated TX test value out of limits
 - Bluetooth radiated TX test value out of limits
 - Wi-Fi scan test fails
 - Bluetooth ping test fails





Step 1 for BT/Wi-Fi TX/RX RF failure

Look for visible damage
of the BT/WiFi Antenna,
Antenna Contacts and
BT/WiFi circuits





Step 2 for BT/Wi-Fi TX/RX RF failure

- If there is no visible sign of antenna damage and antenna contacts damage, its most likely something wrong in the BT/Wi-Fi chips or circuits.
- Open up the shield and look for misplaced or damaged RF front-end components. Please refer to the previous slide describing the layout of the WLAN circuit.
- It is recommended to probe the amplitude of the TX signal along the RF path to look for the failure component.





FM TROUBLESHOOTING



MOTOROLA CONFIDENTIAL

Moto G (3rd Generation)
TROUBLESHOOTING GUIDE



Debugging FM RSSI Failure

If FM RSSI is out of limits

1. Check whether the headset connection between the phone and the FM signal generator are correctly done
2. Check and make sure that the headset jack is not damaged
3. Check there is no damage on audio flex, and audio flex is well inserted into connector J4900
4. Then check for any visible damage around the FM antenna/Antenna matching components
5. (For non-DTV variant) Open up the DTV shield and check whether R6010F placed correctly
(For DTV variant) Open up DTV shied and check whether C6015, C6014, L6015, S6010, R6011 placed correctly, and check S6010 voltage 2.85V





Debugging FM RSSI failure

If FM RSSI is out of limits


6. Then open up the WIFI/BT shield and check whether the FM Rx matching components placed correctly/damaged
7. Then Check connections between WCN3620 and MSM8226:

FM: no probing point – use x-ray or other means to make sure following is soldered properly


- Pins 50 of U4600 (FM Rx RF line)
- Pins 41 and 46 of U4600 (these are connection points of SSBI and DATA lines)



FM Frontend (Non-DTV Version)




FM Frontend (DTV Version)



MOTOROLA CONFIDENTIAL

Moto G (3rd Generation)
TROUBLESHOOTING GUIDE

FM Rx Matching




MOTOROLA CONFIDENTIAL

Moto G (3rd Generation)
TROUBLESHOOTING GUIDE


FM Part Placement/Routing



Matching components



Frontend components





DTV TROUBLESHOOTING




MOTOROLA CONFIDENTIAL


Moto G (3rd Generation)
TROUBLESHOOTING GUIDE



DTV Schematic - 1



DTV Schematic - 2





Debugging DTV RSSI Failure

If DTV RSSI is out of limits

1. Check if the headset connection between the phone and the DTV signal generator are correctly done
2. Check and make sure if the headset jack is not damaged
3. Check if there is any visible damage around the SPDT S4750 and around components
4. Probe the amplitude of the TX signal along the RF path to look for the failure component
5. Check 37.4MHz XO output Y4750
6. Check the voltage
 - DTV_1P2V_EN: R4756 1.8v
 - Vreg_L17_2P85: C4765 should be 2.85v
 - Vreg_L6_1P8: C4755 should be 1.8v
 - DTV_RF_DIG_LDO_IN: C4757 should be 1.8v
 - DTV_DIG_LDO_OUT: C4756, E4751 should be 1.1v
7. Check X-ray if any solder issue under U4750 (DTV FC8300W)





POWER UP FAILURE TROUBLESHOOTING



MOTOROLA CONFIDENTIAL


Moto G (3rd Generation)
TROUBLESHOOTING GUIDE



Power Up Failure Troubleshooting

Phone power could be triggered on with different reasons. Here we assume it is triggered by the power button press.


1. Before any action, the PMIC need to see a valid BATT+ (2.5V to 4.3V), and B+ should be the same as VBATT. If using a battery eliminator, you would see about 50~100uA (off current) being consumed. PMIC is alive, ready to work. BATT+ being 2.5V will power up PMIC but to start a full power up sequence for the phone, SW need to see BATT+ at 3.6V.
2. Power button is pressed. This is a mechanical button. If pressed, the PMIC should receive a low voltage at pin K10. You can verify it at a resistor **R5031** or a **test point below**. If this signal does not get lower, likely the button is failing.





Power Up Failure Troubleshooting


3. At this moment, the PMIC will check the battery voltage. It needs to be higher than 2.7V (default UVLO) to move forward. If the voltage is lower, or the PMIC is locked, (internal logic is messed up), you would see only a tiny current 2mA rises and falls, when you press the power button.
4. A power up sequence is started. From regulator Vreg_S4, to Vreg_L5, one by one, the regulator comes up. And then the PMIC clock comes up and feeds to MSM. Check the picture for reference.





Power Up Failure Troubleshooting

5. After the clock is ready, PMIC continues booting up sequence, until VREG_L11 is available.
6. PMIC will **pull up** the PON_RESET_N to inform MSM to start to work. A test point **TP_MSM_RESET_N** can be used to verify the signal PON_RESET_N. MSM will run the primary boot load SW.
7. MSM responds back by **pulling up** PS_HOLD, telling PMIC to keep power up. **R2001** can be measured to verify this signal.





Power Up Failure Troubleshooting

8. The rest of the regulators are turned on based on SW. SW will check the environment to see if it need to continue to power up. For example, if the BATT+ is lower than 3.6V, SW will decide to turn off the power, because battery energy is not sufficient to do a meaningful power up.
9. At this moment, if there is an issue in the SW (may or may not be HW related), PS_HOLD could be pulled lower to shut off the power, if the PS hold timer is still working. If not, then phone is stuck and freezing. SW log is critical for the troubleshooting in this case.
10. Some other possible reasons for power failures include, peripheral communication failure, memory failure, SW loading failure, etc.

Note: Some easy things to check. If the board consumes more than 100uA off current, find out what is causing the higher off current. If the PMIC is draining high off current, likely PMIC is bad and its internal logic is messed up. Replace the PMIC. Here are some pins to measure, REF_BYP at C2001, AVDD_BYP at C2002, and the above signals in the power up steps.





Power Up Failure Troubleshooting




Figure 3-8 Poweron sequence





CHARGING TROUBLESHOOTING



MOTOROLA CONFIDENTIAL


Moto G (3rd Generation)
TROUBLESHOOTING GUIDE

Charging Troubleshooting



- (Charge Path 1/2):


USB Connector M5001-> Charger IC U5201 (pin A5, B5) -> L540 -> Charger IC U5201 (pin D3, E3)




Charging Troubleshooting

- Charge Path (2/2):

-> Charger IC U5201 (pin D3, E3) -> Charger IC U5201 (pin D4, E4) -> R5201 -> Battery Connector P5200 (pin 1)





Charging Troubleshooting

In the event of charging issues:

- Do visual inspection on USB connector and battery connector.
- Check charging voltages along the charging path
 - Measure USB_PWR charger input voltage at D5001. The voltage should be between 4.3V ~ 6V.
 - Check B_PLUS voltage at C548. It should be 4.35V or lower.
 - Check battery voltage at P5200 pin1. It should be 4.35V or lower. If battery is below 2.1V, there maybe a short in the circuit somewhere and the battery protection circuit is triggered.
 - Check battery ground path R5205.
- Battery temperature should be between 0°C ~ 45°C to be fully charged. Check thermistor voltage at test point (TP_BAT_THERM). It should be around half of battery voltage at room temperature (25°C).





LED / VIBRATOR / USIM / microSD TROUBLESHOOTING




MOTOROLA CONFIDENTIAL

Moto G (3rd Generation)
TROUBLESHOOTING GUIDE



SOL (Sign of Life) LED

- SOL LED is driven by U2000 PM8916 CHG_LED_SINK (pin M13) and B_PLUS
- Note: LED is being used only for SOL functionality. Notification LED functionality is not being used and will display the message on the LCD display.





White SOL LED

In the event of SOL LED issue:

- Check voltage at LED Anode (pin 2) and Cathode (pin 1) of D5401A
- LED Anode voltage = B_PLUS (3.2V to 4.3V) and Cathode voltage = ~(B_PLUS – 3.1V LED forward voltage)





Rotary Vibrator

Rotary vibrator is used for both haptic and vibration alert function. In the event of vibrator failure:

- Inspect physical placement of rotary vibrator related components on main PCB board (see schematic page on next slide)
- Check voltage on pin 2 and 1 of vibrator M5100: Pin 2 Voltage = B_PLUS. Pin 1 voltage will be driven by U2000 PM8916 pin M14.
- When vibrator is active (being driven), the voltage delta between pin 1 and pin 2 of the vibrator should be around 2.4V. When vibrator is not being driven, voltage at pin 1 and pin 2 are about the same.




Rotary Vibrator



ROTARY VIBRATOR

REF 5100-5119

M5100
59014017003
FZ-1537




MOTOROLA CONFIDENTIAL

Moto G (3rd Generation)
TROUBLESHOOTING GUIDE


SIM



- Depending on the PCB board variant (Single SIM vs. Dual SIM), there are up to 2 SIM connectors on Moto G (3rd Generation) placed on a Daughterboard connected to the main PCB board via 40 pin B2B connector.
- Each SIM connector is operated independently with its own power, detection and SIM bus interface.



Daughter Board SIM Connector





SIM

In the event of SIM issue:


- Do a thorough visual check on SIM connector J5500/J5520 for any sign of mechanical contact issues, FM, solder breaks.
- Inspect all SIM circuit components on PCB (daughter and main board).
- Check SIM power at J5500/J5520 pin C1.
- Check the UIMX_PRESENT line for card detection. Ensure the line toggles after each insertion or removal of the SIM card. (HIGH when SIM card is inserted)
- Check SIM bus interface signal activities during SIM access (UIMx_RST, UIMx_CLK, UIMx_DATA). During normal operation after power up, the clock runs at 3.85 MHz, reset is high, and the SIM bus operates at 1.8V or 3V.






microSD

- Moto G (3rd Generation) supports one microSD connector placed on a Daughter board connected to the main PCB board via a 40-pin B2B connector.





Daughter Board microSD Connector





Main board - Power supply and Card Detect

SD CARD POWER SUPPLY



MOTOROLA CONFIDENTIAL

Moto G (3rd Generation)
TROUBLESHOOTING GUIDE



microSD

In the event of microSD issue:

- Do a thorough visual check on the daughter board's microSD connector J5800 for any sign of mechanical contact issues, FM, solder issues.
- Inspect all microSD circuit components on PCB (main and daughter boards).
- Check microSD power (2.85V) at J5800 pin 4 or C5804.
- Check microSD card detection signal at J5800 pin 10 or VR5801 (active LOW when microSD card is inserted).
- Check for activity on microSD bus interface signals during microSD access (SDC2_CLK, SDC2_CMD, SDC2_D[3:0]).





SENSORS TROUBLESHOOTING



MOTOROLA CONFIDENTIAL

Moto G (3rd Generation)
TROUBLESHOOTING GUIDE



IR Proximity Sensor – Ambient Light Sensor


IR Proximity & Ambient Light Sensor circuit is located on a flex (audio/IR flex combination). This flex is connected to the main PCB board via a zip connector. In the event of IR proximity or ambient light sensor issue at phone level:

- Inspect the zip connector on main PCB board
- Check physical connection of zip connector and flex
- Rework zip connect or replacing the flex as needed





Proximity/ALS Sensor



MOTOROLA CONFIDENTIAL


Moto G (3rd Generation)
TROUBLESHOOTING GUIDE

Proximity/ALS Sensor



*PROX SENSOR/ALS INTERFACE

REF: 6190-6199
I2C ADDR: 0X39



MOTOROLA CONFIDENTIAL

Moto G (3rd Generation)
TROUBLESHOOTING GUIDE




Accelerometer

There are 2 accelerometers IC's on the main PCB boards: primary U9710 and secondary U9711.

In the event of accelerometer failure:

- Inspect physical placement and orientation of U9710 and U9711 and their related components on main PCB board (see accelerometer schematic page on next slide)
- Check power: ACCEL_VDD (1.8V) at pins 1 and 5 of each accelerometer
- Check for activity on the shared I2C interface (SCL_SENS and SDA_SENS) for activity
- Connect the board to a display and power the board/display with a battery or factory cable. Launch the CQA app and test each accelerometer one at a time (CQA Menu Mode -> Sensor -> “Accelerometer” or “Accelerometer Secondary”). Look for accelerometer G-force activity on all axis X,Y,Z.
 - As you move the board’s orientation, the X,Y,Z accelerometer readings will change (representing a vector of approximately $1G = 9.8 \text{ m/s}^2$). An ideal accelerometer IC will display a G-force reading of ~ 9.8 next to “Total Acceleration”. If no data is shown, then the IC may be faulty.
- Check the interrupt line, which is buried: ACCEL_INT / ACCEL_INT_2
- Make sure the sensor hub (U6000) is working correctly: see the “Sensor Hub” section






Accelerometer

ACCELEROMETER

REF: 9710-9719



MOTOROLA CONFIDENTIAL

Moto G (3rd Generation)
TROUBLESHOOTING GUIDE



Magnetometer

There is one magnetometer IC (U6160) on the main PCB board.

In the event of a magnetometer failure:


- Inspect physical placement and orientation of U6160 and its related components on main PCB board (see magnetometer schematic page on next slide)
- Ensure the magnetometer's glass package is not cracked (improper factory handling could cause cracks since there's no shield over the magnetometer)
- Check power: MAG_VIO (1.8V) at U6160 pins B1 and C4
- Check for activity on the I2C interface (I2C_SCL_SENS_MSM and I2C_SDA_SENS_MSM)
- Connect the board to a display and power the board/display with a battery or factory cable. Launch the CQA app and test each accelerometer one at a time (CQA Menu Mode -> Sensor -> Magnetometer). Look for magnetometer activity on all axis X,Y,Z.
 - As you move the board's orientation, the X,Y,Z accelerometer readings will change. Each x,y,z axis for an ideal magnetometer IC will display its greatest positive value when that axis is aligned with magnetic north. If no data is shown or the data isn't changing values, then the IC may be faulty.
- Check the reset and interrupt lines, which are buried: MAG_RESET_N and COMPASS_INT



Magnetometer

MAGNETOMETER

REF: 6160-6169



MOTOROLA CONFIDENTIAL

Moto G (3rd Generation)
TROUBLESHOOTING GUIDE



Hall Effect Sensor

There is one hall effect sensor IC (U6170) on the main PCB board.

In the event of a hall effect sensor failure:


- Inspect physical placement and orientation of U6170 and its related components on main PCB board (see hall effect sensor schematic page on next slide)
- Check power: VDD_HALL (1.8V) at U6170 pin 4
- Check that the sensor reports the presence of nearby magnetic fields. Do this by floating the north side of a magnet directly over the sensor **but on the opposite side of the main board**. The sensor is on the bottom/battery side of the PCB, while the magnet must be held over the sensor on the opposite/display side of the main PCB. When this is done, the display will turn off. The display will turn back on once the magnet is moved far enough away.
- Make sure the sensor hub (U6000) is working correctly: see the “Sensor Hub” section



Hall Effect Sensor



HALL EFFECT
REF: 6170-6179





Sensor Hub

The sensor hub (U6000) on the main PCB board receives data from the dual accelerometers and the hall effect sensor and then routes that data to the MSM. If the sensor hub is not working correctly, then the MSM will NOT receive data updates for the accelerometers and the hall effect sensor.

Therefore, if both the accelerometers and the hall effect sensor are failing all at the same time, then this would be a good indication that it's due to a bad sensor hub (please see the accelerometer and hall effect sections for instructions on how to use the CQA test app to check for accel functionality and how to use a magnet's north pole to verify the hall effect sensor).


In the event of a sensor hub failure:

- Inspect physical placement and orientation of U6000 and its related components on main PCB board (see hall effect sensor schematic page on next slide)
- Check power inputs at: U6000 pins A5, F1, and D5
- Check the active-LOW reset line (STM_NRST): should be high for normal operation
- Check the 32 KHz clock (CLK_XMCS) at U6000 pin A6 (buried line)
- Use x-ray to check for shorts under the sensor hub IC





Sensor Hub



MOTOROLA CONFIDENTIAL

Moto G (3rd Generation)
TROUBLESHOOTING GUIDE



TOUCH TROUBLESHOOTING



MOTOROLA CONFIDENTIAL

Moto G (3rd Generation)
TROUBLESHOOTING GUIDE




Touch Design

- Single Layer Touch On Display
 - INX (Innolux)
 - On-Cell (similar to DVX or Styx)
 - Synaptics S2316
 - 13 TXs * 28 RXs
 - TDI (Taiwan Display Inc.)
 - In-Cell (similar to Lux/Lynx)
 - Synaptics S3346
 - 27 TXs * 15 RXs




Mechanical


For INX There are 13 X channels (Tx) and 28 Y



(CF = color filter)
Panel is facing user. FPC bonding area is next to speaker port at top of phone. In this image it is toward bottom.



REFERENCE SPEC.
71014125001
FOR FLEX PIN OUT
MATE WITH
HIROSE CONN.
FH35C-41S-0.3SHW
MOTO PN 09014084006



Touch flex connects to the main flex via an 9-pin ZIF connector




MOTOROLA CONFIDENTIAL


Moto G (3rd Generation)
TROUBLESHOOTING GUIDE

Electrical

Touch
analog
VDDA
Load
switch
3.3V.



I2C lines (SCL, SDA) should be pulled up to 1.8V





Troubleshooting

- No touch or abnormal touch:
 - 1) Check power supply voltages - VDDA (C5332) = 3.3V, VREG_L6_1P8 = 1.8V
 - 2) Check that a touch on the screen causes a low on TOUCH_INT_N
 - 3) Check touch Zif connector on LCD flex and main PCB for proper insertion or damage
 - 4) Check the module & firmware version in a command window
 - a. “adb shell cat /sys/bus/i2c/devices/2-0020/ic_ver” will output
 - Product ID: s3346b
 - Build ID: 1b5aff
 - Config ID: 27011520
 - Where Product ID: s3346 = TDI, Product ID:s2726 = INX or BOE
 - 5) If above tests pass, check for a panel crack





DISPLAY TROUBLESHOOTING




MOTOROLA CONFIDENTIAL

Moto G (3rd Generation)
TROUBLESHOOTING GUIDE




Display Circuit Location



Display Signal Check




Green components placed, Red components NOT placed






Backlight Driver Signal Check

Green components placed, Red components NOT placed





CABC Signal as seen on an oscilloscope



MIPI signal as seen on an oscilloscope (zoomed out)



MOTOROLA CONFIDENTIAL

Moto G (3rd Generation)
TROUBLESHOOTING GUIDE

MIPI signal as seen on an oscilloscope (zoomed in)



MOTOROLA CONFIDENTIAL

Moto G (3rd Generation)
TROUBLESHOOTING GUIDE




CAMERA TROUBLESHOOTING



MOTOROLA CONFIDENTIAL

Moto G (3rd Generation)
TROUBLESHOOTING GUIDE

Camera Troubleshooting



MOTOROLA CONFIDENTIAL

Moto G (3rd Generation)
TROUBLESHOOTING GUIDE





Main Imager

- The image sensor is a color CMOS image sensor with Bayer (blue, green, green, red) pattern filter.
- The sensor is 13MP.
- This module has an Auto Focus (AF) module with integrated driver (VCM).
- Data interface: Dual serial (1 pair-clk, 4 pair-data) mobile industry processor interface (MIPI). I2C is used for control.
- Analog Supply regulator (2.8V) located on Main PCB.
- Digital Supply regulator (1.05V) located on Main PCB.
- Full 1080P video mode
- Zero Shutter Lag





Main Imager






MOTOROLA CONFIDENTIAL



Moto G (3rd Generation)
TROUBLESHOOTING GUIDE



Main Imager (cont.)



CAMERA VDDIO - 1.8V




MOTOROLA CONFIDENTIAL

Moto G (3rd Generation)
TROUBLESHOOTING GUIDE



Main Imager Pinout (Looking through PCB)





Main Imager Troubleshooting


Troubleshooting Tips:

- Check CAM_R_DVDD (digital) = 1.05V
- Check CAM_R_VDDIO supply = 1.8V
- Check CAMR_A_REG (analog) = 2.8V
- Check CAMR_AFVDD supply = 2.8V

- Check MIPI data/clk exist on all lines

After imager APP is launched.

- Check reset is high (1.8V)
- Check I2C clk/sda activity is present.
- Check Main reference clk = 23.8Mhz







Front Facing VGA Imager

- The Front Facing (FF) imager is VGA.
- The sensor is a color CMOS SOC image sensor with Bayer (Green, Red, Green, Blue) pattern filter.
- The sensor is 5MP - Preview, Capture and video.
- The Module is capable of auto exposure, white balance, color correction, and color conversion.
- This device provides a finished image at up to 30 fps.
- Analog Supply regulator (2.8V) located on main transceiver PCB.



Front Facing VGA Imager




MOTOROLA CONFIDENTIAL


Front Facing VGA Imager (cont.)




CAMERA ANALOG FRONT - 2.85V





CAMERA FRONT DVDD - 1.2V



EMI / ESD FILTER




PLACE E5620 AND C5620 NEAR MSM





Front Facing VGA Imager






Front Facing VGA Imager Troubleshooting

Troubleshooting Tips (with Imager on):

- Check CAM_A_FRONT (analog) = 2.8V
- Check VDDIO logic supply = 1.8V
- Check CAM_F_DVDD (digital) = 1.2V
- Check MIPI data/clk exist on all lines

After imager APP is launched.

- Check reset is high (1.8V)
- Check I2C clk/sda activity is present
- Check Main reference clk = 23.8MHz



MOTOROLA CONFIDENTIAL

Moto G (3rd Generation)
TROUBLESHOOTING GUIDE



Flash LED and Flash LED Drive


- Flash LED uses two LEDs that are placed on the Flash PCB, see next slide for a picture
- The flash LED drive resides on the main board, see next slide for a picture






Flash LED and Flash LED Drive

- Flash LED uses two LEDs that are placed on the Flash PCB as shown below



Flash PCB Top Side





Flash PCB Top Side





Flash LED and Flash LED Drive




- Flash LED PCB make contacts through four spring contacts that are on the daughter card as shown below





Flash LED and Flash LED Drive

- Flash LED Drive resides on the main PCB and the output of the driver goes to the daughter board then through the spring contacts to the FLASH PCB as shown below





Flash LED and Flash LED Drive

Troubleshooting:

- 1) Check input voltage to the Flash LED drive – B_Plus at C6132, ensure it within the limits of B_Plus as it varies depending on the battery level or supplied voltage
- 2) Check the output voltage of the driver (anode of the Flash LEDs) during torch to be around 2.8V and during strobe around 3.6V
- 3) Check I2C interface of the Flash LED drive (I2C_SDA_cAM and I2C_SCL_CAM)
- 4) Ensure that the Flash PCB is making contacts with the daughter card





AUDIO TROUBLESHOOTING



MOTOROLA CONFIDENTIAL

Moto G (3rd Generation)
TROUBLESHOOTING GUIDE



Audio Devices

Main Microphone

Uses:

- Speech in handset and speakerphone mode

Port thru main
speaker opening

Front of the phone



Secondary Microphone

Uses:

- Noise suppression for voice calls
- Multimedia audio recording

Top Ported



Back of the phone





Mic Locations and Functions


Earpiece

Earpiece

Uses:

- Low Audio

Port thru front lens



Main Speaker

Uses:

- Speakerphone

Port thru front lens



MOTOROLA CONFIDENTIAL

MOTO G (3rd Generation)
TROUBLESHOOTING GUIDE



“No Audio” Complaints

- The CQA apk can be used to verify a broken audio path. Under the “Audio” menu, select “Mic Loopback”.
 - The “Primary MIC” setting loops mic1 to the earpiece.
 - The “Secondary MIC” setting loops mic2 to the earpiece.
- If both of those are not function, the earpiece speaker path may be damaged. In the “AUDIO” menu of the CQA apk, select “Ear Speaker” and then “Play Harvard speech pattern”.
- The loudspeaker can be tested by selecting “Loudspeaker via the CQA apk. Music should start playing.
- Loudspeaker functionality can be checked quickly by playing a ringtone.




Primary Microphone



PRIMARY MIC

REF: 5700-5709



MOTOROLA CONFIDENTIAL

Moto G (3rd Generation)
TROUBLESHOOTING GUIDE



Primary Microphone

If the Primary mic is not functioning...

Check mic bias at L5700 or C5704. This should be 2.1V when the microphone is enabled.

Check the microphone assembly to make certain it is not damaged, which may indicate a broken diaphragm.

Check the microphone output at C5700 or C5701. The AC amplitude should increase when audio is present.




Secondary Microphone



SECONDARY MIC (FLUENCE/ANC NOISE MIC)

REF:5750-5759



MOTOROLA CONFIDENTIAL

Moto G (3rd Generation)
TROUBLESHOOTING GUIDE



Secondary Microphone

If the Secondary mic is not functioning...

Check mic bias at R5753 or C5753. This should be 2.1V when the microphone is enabled.

Check the microphone assembly to make certain it is not damaged, which may indicate a broken diaphragm.

Check the microphone output at C5751 or C5750. The AC amplitude should increase when audio is present.





Primary Microphone Seal

If Primary microphone seal is broken:

- 1.) Open CQA app.
- 2.) Under the “Audio” menu, select “Mic Loopback”.

The “Primary MIC” setting loops mic1 to the earpiece.

- 3.) Listen for primary mic audio in handset earpiece.
- 4.) Block the primary mic port, listen audio in earpiece. If primary mic is sealed, there will be no /very low audio in Handset earpiece.

If primary mic seal is broken, block and unblock audio level almost same.





Second Microphone Seal

If Second microphone seal is broken:

- 1.) Open CQA app.
- 2.) Under the “Audio” menu, select “Mic Loopback”.
The “second MIC” setting loops mic2 to the earpiece.
- 3.) Listen for second mic audio in handset earpiece.
- 4.) Block the second mic with tape, listen earpiece audio. If second mic is sealed, there will be no/very low audio in Handset earpiece.

If second mic seal is broken, block and unblock audio level almost same.




Earpiece



EARPIECE TRANSDUCER

REF: 5780-5789



MOTOROLA CONFIDENTIAL

Moto G (3rd Generation)
TROUBLESHOOTING GUIDE



Earpiece

- The earpiece circuit is placed on the daughter board.
- The earpiece speaker have series 0.096uH inductors (L5782, L5783) components. There are shunt components to ground that can be checked (C5786, C5787, and VR5784,VR5785).
- The earpiece speaker has a nominal impedance of about 32Ω .
- This is a linear amplifier output, where playing a tone would produce a clean AC output voltage.






Loudspeaker

LOUDSPEAKER

REF:5780-5789




MOTOROLA CONFIDENTIAL

Moto G (3rd Generation)
TROUBLESHOOTING GUIDE



Loudspeaker

- The loudspeaker can be probed at L5780 and L5781
- The impedance of the loudspeaker should be around 8Ω when probing on the component
- The output is a class D waveform (sample wave shown below)






3.5mm Headset Jack

3.5MM HEADSET

SENSOR HUB HEADSET DETECTION CIRCUIT






3.5mm Headset Jack

AUDIO JACK DETECTION

REF:4800-4849




MOTOROLA CONFIDENTIAL

Moto G (3rd Generation)
TROUBLESHOOTING GUIDE

3.5mm Headset Jack

REF: 4900-4949





HEADSET JACK TROUBLESHOOTING



MOTOROLA CONFIDENTIAL

Moto G (3rd Generation)
TROUBLESHOOTING GUIDE



Phone Level Headset Troubleshooting

- When no headset Inserted:

Measure voltage at Sleeve_Jack ,voltage should be around 2.3 volt.

- When headset is Inserted:

Measure voltage at Sleeve_jack, voltage should be around 1.07 volt
~2.4volt(depending on mic impedance of the headset used)





PCB Level Troubleshooting

- **Measure voltage at pin 3 of (LDO) U4920.**

If pin3 voltage is 1.8 volt,U4920 is enable/ON

If pin3 voltage is 0 volt,U4920 is disable/OFF

LDO is only ON when sensor HUB detects headset inserted and turn ON.

LDO is turn OFF by sensor Hub when headset is detected to be removal

- **Measure voltage across Ref Des R4931(HS_ADC):**

When no headset inserted: Voltage across R4931 should be 1.63 volt

When headset inserted: Voltage across R4931 should be 0.73volt~1.63 volt
depending on the headset mic impedance.

