

### Middle East & North Africa Personal Communication Sector

# Field Service Information C650 No Camera Function

Our Reference: SI33 6 2004

Date: June 17, 2004

Pages (including this page): 3

## Prepared by:

Mohamed Morsy Customer Services Manager, Middle East & North Africa

Classification: Motorola Internal Information Strictly released for Motorola Authorized Service Center Use only.



#### Middle East & North Africa

Date: June 17, 2004

Our Reference: SI33\_6\_2004

Product/System: C650

Subject: C650 No Camera Function

## **FIELD SERVICE INFORMATION**


#### **Problem:**

Service has been made aware of a camera issue on the C650 product. The camera module to PCB connector at times will not mate properly, resulting in an intermittent or no camera operation when attempting to capture a photo.

#### Solution:

A redesigned camera module has been implemented in production units. The part number 0170298Z08 changes from a Rev 0 to Rev A. This Rev A module has two modifications from the original design:

1) A poron tape has been added to the top of the module to PCB connector. Refer to the photo below to aid in distinguishing between the Rev 0 and Rev A camera modules:



2) In addition, the soft poron tape under the module has been changed to hard acrylic.

**Classification:** 

Motorola Internal Information Strictly released for Motorola Authorized Service Center Use only.

#### **Field Service Action:**

#### **Customer Returns:**

Perform the following analysis procedure on all returned units with camera-related customer complaints:

- 1) Disassemble the unit to gain access to the camera module;
- 2) Verify that the module has the poron tape installed on the camera flex as shown in the above photo. Replace with a Rev A module if necessary.
- 3) Reassemble the unit and test camera operation.

#### **Warranty claim Codes:**

Please ensure that repairs of this type are logged on to the applicable database as follows:

**Global Service Codes-**

Customer Complaint: CAM02 Camera-No Function Problem Found: CON05 Connectors-Module

Reference Designator: CAM Camera

Repair: RCA02 Replace Camera-Mechanical Fault

Classification: Motorola Internal Information Strictly released for Motorola Authorized Service Center Use only.