

Consumer Solutions & Support US Competency Center 600 North US Highway 45 Libertyville, Illinois 60048 Website: gs.mot.com

FIELD SERVICE BULLETIN

FSB Number:	LVCCFSB2004-155
Author:	Hien Huynh
Date:	July 20, 2004
Total No. of Pages:	3
Subject:	GSM E398 – Loose Battery door fit.
Model Affected:	E398
Level of Repair:	2

<u>Problem</u>

This is an informational bulletin detailing a hardware change on E398. The hardware change is to address two issues:

- 1) To improve X axis movement of the battery door performance.
- 2) To improve Y axis movement of the battery door performance.
- 3) To improve Z axis battery door squeeze. See photo 1, 2 & 3 below for illustration.



X axis- battery door side movement.

Photo 1



Y axis- battery door side movement. Photo 2



Consumer Solutions & Support US Competency Center 600 North US Highway 45 Libertyville, Illinois 60048 Website: gs.mot.com



Z axis- battery door up & down movement.

Photo 3

Solution

Corrective action was implemented to improve Battery door fit:

- Battery door revision "O" or "B" with battery door revision "D"; *fixed Z, X and Y axis movement.*

This solution had been implemented and cut over plan in middle of July 2004.

Photo & part numbers are shown below for reference:



Battery Door	Part number
Soft touch Black	SHN8650A
Cosmic Universe Blue	SHN8649A
Star White	SHN8651A

Battery door Revison is located here

Field Service Action

Customer Returns:

If an E398 unit is returned for loose battery door then replace with:

- Battery door revision "O" or "B" with battery door revision "D".



Consumer Solutions & Support US Competency Center 600 North US Highway 45 Libertyville, Illinois 60048 Website: gs.mot.com

Service Inventory:

N/A Service Entry Codes

Please ensure that repairs of this type are logged in the service database as follows:

PRC Codes: Customer Complaint Code: 4101 – Battery Door Fit / Gap Repair Code: 1206 – Replace Part –CSB / FSB

Asia Codes:

Fault Code:28 – Housings don't fit together properlyRepair Code:11– Housing Issue – Known design issue

M-Claim Codes:

Customer Complaint Code: HBD01 – Battery Door Fit / Gap Problem Found Code: HRE03 – Housing Rear – Poor Fit Ref. Des. Code: H – Housing Repair Code: RPT06 – Replace Part – CSB/ FSB.