

Consumer Solutions & Support US Competency Center 600 North US Highway 45 Libertyville, Illinois 60048 Website: gs.mot.com

FIELD SERVICE BULLETIN

FSB Number: LVCCFSB2005-371
Authors: Darwin Garcia
Date: December 28, 2005


Total No. of Pages: 3

Subject: V3i Bezel Shorting


Model Affected: **V3i** Level of Repair: 2

Problem

Service has been made aware of a V3i Siliqua Bezel Shorting issue were the M logo and Bluetooth LED will always turn on which could cause "Alert - LED, wrong indicator" complaints. The symptom will show when the SIM cards and the battery are in placed, even without turning on the phone.





The root cause was determined to be P-Flex within flip shorted with metal bezel due to abrasion with burr on bezel.






Consumer Solutions & Support US Competency Center 600 North US Highway 45
Libertyville Illinois 60048





Solution


The screened inventory will have Kapton tape, a changed bar code and a 'T' mark to denote screening as a short term measure.





Consumer Solutions & Support US Competency Center 600 North US Highway 45 Libertyville, Illinois 60048 Website: gs.mot.com

For screened inventory the bar code changed from Y01/C to Y01/D and the front housing was mark with a "T" on the back.



Flips with new 2 tapes on the external bezel

The vendor will add a new step to remove any "burr" from the bezel as permanent corrective action.

Field Service Action

Customer Returns:

When servicing any V3i customer phones with described issue, the P-Flex must be replaced and kapton tape added. Personality Flex Assy # 8489906Y01

Call Center Action:

Call center should advise callers to send phone for repair.

Service Inventory

N/A

Global Codes

M Claims:

Customer Complaint Codes: ALT09 (Alert - LED, wrong indicator)

Problem Found Code: ALT09 (Alert - LED, wrong indicator) Repair Code: RTW02 (replace level 2 part per FSB/CSB)