

MOTOROLA UK
REDWOOD
CROCKFORD LANE
CHINEHAM BUSINESS PARK
CHINEHAM
BASINGSTOKE
UNITED KINGDOM RG24 8WQ

CSB-1111-2 Country: UK Date: 11/13/2006 APC: ALL Repair Level: 2

Title Model Effected V3 05 CR - GSM - Earpiece Low\_Core magnet mis-aligned V3 05/V3i/V3

#### **PROBLEM**

Service has been awared of an issue identified during the V3 05 MOL analysis. Some units returned with customer complaints of "Audio, Earpiece low", were found the core magnet was misaligned. The resistance is normal (around 30ohm). See the below figure.



The adhesive did not spread evenly over the core magnet, which caused the core magnet to shift and generate low or distorted sound. The poor distribution of adhesive was due to the uneven pressure imposed on the core magnet.

#### SOLUTION

The supplier replaces the hot press machine with the air-powered press machine to press the magnetic field so as to make sure the adhesive is well distributed under even pressure. Start Date: 08/28/2006. Date Code: 06.08.28 (Wk35).

### FIELD SERVICE ACTION

When servicing any customer return of affected models with described symptom, check the earpiece Date Code firstly. If it is before 06.08.28 (Wk35), replace the earpiece. The part No. is 5089574N02. Otherwise, please follow normal troubleshooting procedure to identify the failure per the customer complaint.



## **CALL CENTER ACTION**

When a customer contacts you with a complaint of "earpiece low/distortion", you should advise the caller to have the phone repaired per this FSB at an Authorized Motorola Service Center.

# **SERVICE ENTRY CODE**

## Global Service Codes

Complaint Code: AUD02 - Audio - Earpiece , Low Problem Found Code: AUD02 - Audio - Earpiece , Low

Reference Designator:SPK - Speaker

Repair Code: RTW02 - Replace Level 2 part - CSB/FSB

If applicable, note this bulletin number on warranty claim forms and make necessary changes to service manuals.2006-460 © Copyright 2006 Motorola Inc. All Rights Reserved.

Close | Print