# FIELD SERVICE BULLETIN

FSB Number FLCCFSB2008 - 57 Author Lutz Neumann

Date Tuesday, February 26, 2008

Subject 3G - MOTORIZR Z8 - No Display, Audio-no MIC, No turn on, Camera -

image view

Model Affected MOTORIZR Z8

Level Of Repairs 3

#### **Problem**

Service is aware of an issue identified during the evaluate of the MOTORIZR Z8 NPI returns. Some units returned with complaints like:

- · Display flickering
- · Display no display
- Audio no microphone
- Audio earpiece distortion (while audio/video record)
- Camera distorted imageview
- Turn on/off no turn on.

Analysis identified a faulty dynamic flex with part No. 0103664E02 (8403658D04P4\_E).



#### **Solution**

The design of the Dynamic Flex (DYF) has been improved and is available with Part No. 0103664E13 (8403658D13).

#### **Field Service Action**

If servicing MOTORIZR Z8 with the customer complaints mentioned above (or similar), then

- open the Z8 and follow up with the disassembling procedure mentioned in the service manual.
- check the Part No. of the assembled DYF as show on the picture above and exchange it to the DYF Ref 13 with the Part No. 0103664E13.
- reassemble the unit and test it for functionality.

If the change of the DYF doesn't fix the issue, then follow normal troubleshooting techniques per the Customer Complaint.

### **Service Inventory**

The DYF Ref 13 (0103664E13) is available for order since wk8/2008.

#### **Call Center Action**

When responding to customer inquires on phones related to "Display - flickering", "Display - no display", "Audio - no mic/ or distortion", "Camera - distorted imageview" or "Turn on/off - no turn on", please inform the customer to return the unit to a Motorola Service Center for repair, per this FSB.

# **Service Entry Code**

### **Global Service Codes**

Complaint Code: AUD01 - Audio - Earpiece, No

AUD15 - Audio - Earpiece, Distortion CAM11 - Camera - Picture View DIM01 - Display Main - No display TON01 - Turn on/off - No Turn On

Problem Found Code: AUD01 - Audio - Earpiece, No

AUD12 - Audio - Mic Noisy at Unknown Cond

CAM01 - Camera - Poor Quality DIM01 - Display Main - No display TON01 - Turn on/off - No Turn On

Reference Designator:FLEX - Flex

Repair Code: RMP01 - Replace Mechanical Part - Defective