

Consumer Solutions & Support US Competency Center 600 North US Highway 45 Libertyville, Illinois 60048 Website: gs.mot.com

Website: gainoticoi

Informational FIELD SERVICE BULLETIN

FSB Number: LVCCFSB2005-143 Rev B

Author: Dale Jenkins Date: May 19, 2005

Total No. of Pages: 3

Subject: GSM Mid-Tier - Placement of Liquid Detection Labels

Model Affected: V300, V303, V400, V500, V505, V525, V600

E550/V535, V550/V545, V620/V600i, V635

V547, V551, V555, and V330

Level of Repair: 2

Problem

Service is aware of an issue, identified during the NPI Analysis of the GSM V635 product. Some units, returned with complaints relating to a soft-reset, were found to contain a software panic code for SIM Bounce Detect Error. During analysis of these units, the development team noted there was a concern with the placement of the Liquid Detect Label being near the SIM Card Connector. Slight variations in the placement could interfere with and reduce the amount of contact pressure of the SIM Card, which may increase the susceptibility to a SIM Bounce occurrence.



Fig. 1.0 - "Bad" Placement

Solution

As of April 29th 2005, all factories producing the models (V300, V303, V400, V500, V505, V525, V600E550/V535, V550/V545, V620/V600i, V635) are placing the liquid detection label on the shield in the upper section of the board near the antenna port. See image (Fig. 2.0 – "Good" Placement) below.

For San2rini models (V547, V551, V555, and V330) see image (Fig 3.0 -San2rini WDL Placement) below.



Consumer Solutions & Support US Competency Center 600 North US Highway 45 Libertyville, Illinois 60048 Website: gs.mot.com

Note: The exact position may vary slightly on the shield.




Fig. 2.0 - "Good" Placement




Fig 3.0 -San2rini WDL Placement

Service Action

Customer Returns:

When performing services on any GSM model, listed, that requires the rear housing to be removed allowing access to the water detection label. Remove label that has been placed in SIM card area and place a new label (Part # 5485042F01) on the shield in the indicated location. See images above.

Service Inventory:

No action required

Call Center Action

No action required

Service Entry Code

M Claims: N/A