


MOTOROLA UK REDWOOD CROCKFORD LANE CHINEHAM BUSINESS PARK CHINEHAM BASINGSTOKE UNITED KINGDOM RG24 8WQ

CSB-1357-2 Country: UK Date: 6/20/2007 APC: F77 Repair Level: 2

Title Model Effected C168/C168iW220 - GSM - No Alert due to Speaker damaged C168,C168i,W220

### **PROBLEM**

Service is aware of an issue identified during the W220 MOL analysis. Some units, returned with a customer complaint of 'Alert-Ring tone, No/Low/Distortion', were found the alert speaker coil scramble. Further analysis revealed that the gule around the wire thaw and cause scramble.



# SOLUTION

Vendor AAC replaced new wire of high temperature glue, and implemented from data code of 0717. Part number is MESCY61006A



## FIELD SERVICE ACTION

For W220 phones returned to Service Center with the customer complaint of 'Alert.Ring tone, No/Low/Distortion', please check if the speaker is failed.

If yes, then replace a new speaker.

If the speaker is good, please perform the normal troubleshooting.

#### Service Inventory

Advise running change the inventory.

### CALL CENTER ACTION

User complaint of 'Alert, Ring Tone, No/Low/Distortion' on W220 and C168 may be caused by speaker failed. When a customer contact you with this complaint, then tekk the customer to bring the handset to Motorola Certified Service Center for repair.

### SERVICE ENTRY CODE

# Global Service Codes

Complaint Code: ALT01 - Alert - Ring tone, no

ALT02 - Alert - Ring tone, low

ALT03 - Alert - Ring tone , noise / distortion

Problem Found Code: ALT01 - Alert - Ring tone, no

ALT02 - Alert - Ring tone, low

ALT03 - Alert - Ring tone , noise / distortion

Reference Designator:AL - Alert

Repair Code: REP01 - Replace Electrical Part - Defective

If applicable, note this bulletin number on warranty claim forms and make necessary changes to service manuals.2007-198 © Copyright 2007 Motorola Inc. All Rights Reserved.

Close | Print