



Motorola Mobility LLC  
 222 West Merchandise Mart Plaza  
 Suite 1800  
 Chicago, IL 60654, USA  
 Website: <https://motorola-global-portal.custhelp.com/app/mymotorola/portal>


## **INFORMATIONAL FIELD SERVICE BULLETIN**

FSB Number	CHRAEFSB2018-4
Author	Ross Karlen
Date	01/12/2018
Subject	Moto X4 - Moto Key - Incorrect Update Link
Model Affected	None
Level Of Repairs	Level 1



### **Problem:**

Motorola is aware of a customer experience issue on the Moto X4 where a customer had set up Moto Key while on N software release and upgrade to O release. Customer will be unable to unlock computer after upgrade to O release and be instructed to update their Moto Key application on their PC. When attempting to upgrade customer will be sent to an incorrect link.

**Initial Device Condition of Moto X4 – MotoKey on phone setup with Windows PC**




Phone




Windows PC


# Moto X4 Phone Upgrade – Phone gets Android O software OTA upgrade




## USECASE 1 - User attempts PC unlock using MotoKey after Android O upgrade



User Manually  
Unlocks  
Windows PC




**PROBLEM :** Click on Software version out of sync notification popup leads to incorrect URL



**Incorrect URL :** <https://drive.google.com/drive/folders/0B3zZpMGCSNNZQURJSGjNwttcUU?usp=sharing>

**USECASE 2 -** User attempts to use MotoKey with Internet Explorer for Login to Website ( eg: Amazon.com )




**PROBLEM : Click on Update notification popup on the Internet Explorer leads to incorrect URL**



**Incorrect URL : <https://drive.google.com/drive/folders/0B3zZpMGCSNNZC>**


**USECASE 3 - User attempts to use MotoKey with Chrome for Login to Website ( eg: Facebook.com )**



MotoKey website is launched properly ([www.motorola.com/motokey](http://www.motorola.com/motokey))


**No Issues seen**

**USECASE 4 - User attempts to use MotoKey with Chrome / Internet Explorer for Login to Website**




**User Clicks on the taskbar notification**

**PROBLEM : Click on Software version out of sync notification popup leads to incorrect URL**



**Incorrect URL : <https://drive.google.com/drive/folders/0B3zZpMGCSNNZQRJSGjJNWttcUU?usp=sharing>**


## Moto Key software upgrade message seen on Phone – No Issue seen on Phone flow



## Solution:

Provide customer the proper link to update Moto Key - <https://www.motorola.com/moto-key> , inform customer on proper MotoKey version to use based on their device software.

1. Android N users (7.1.1) need to download/install MotoKey 1.0.x software
  - a. Will need to select if 32-bit or 64-bit
2. Android O users (8.0.0) need to download/install MotoKey 2.0.x software
  - a. Will need to select if 32-bit or 64-bit



## **Field Service Action:**

When servicing customer returns for Moto X4 with customer complaints about Moto Key upgrade link not working, then:

1. Instruct customer to upgrade their Moto Key application at the following url: <https://www.motorola.com/moto-key> and inform customer on proper MotoKey version to use based on their device software.
3. Android N users (7.1.1) need to download/install MotoKey 1.0.x software
  - a. Will need to select if 32-bit or 64-bit
4. Android O users (8.0.0) need to download/install MotoKey 2.0.x software
  - a. Will need to select if 32-bit or 64-bit

## **Service Inventory:**

N/A

## **Call Center Action:**

When responding to customers experiencing issue upgrading their Moto Key that use a Moto X4, then:

1. Direct the end user to the following url: <https://www.motorola.com/moto-key>
  - a. Android N users (7.1.1) need to download/install MotoKey 1.0.x software
  - b. Android O users (8.0.0) need to download/install MotoKey 2.0.x software

### **Note:**

Only apply the designated Service Entry Codes, listed in this bulletin, if the unit fails a test or has a customer complaint that matches the issue described in the bulletin

If the unit fails a test or has a customer complaint that does not match the issue described in the bulletin, the Service Entry Codes used should accurately reflect the true problem found

If the unit passes all tests and inspections and does not have a related customer complaint, the Service Entry Code used should be NFF