









Release	Date	Department	Notes to change
1.0	23.08.2005	COM MD CC GRM T	New document

Table Of Contents

1.	CL75 Board Layout	4
2.	System Connector	5
3.	LED	6
4.	Battery Connector	7
5.	Backup Battery	8
6.	Microphone	9
7.	Speaker Spring	10
8.	IRDA	11
9	Hall IC	12

Introduction

This Service Repair Documentation is intended to carry out repairs on Siemens repair level 2.5. The described failures shall be repaired in Siemens authorized local workshops only.

All repairs have to be carried out in an ESD protected environment and with ESD protected equipment/tools. For all activities the international ESD regulations have to be considered.

Assembling/disassembling has to be done according to the latest CL75 Level 2 repair documentation. It has to be ensured that every repaired mobile Phone is checked according to the latest released General Test Instruction document (both documents are available in the Technical Support section of the C-market).

Check at least weekly C-market for updates and consider all CL75 related Customer Care Information.

If you have any questions regarding the repair procedures or technical questions spare not hesitate to contact our technical support team in Kamp-Lintfort, Germany:


Tel.: +49 2842 95 4666 Fax: +49 2842 95 4302

e-mail: st-support@klf.siemens.de

1. CL75 Board Layout


Jigs, Tools and working materials for all described repairs:

- Hot air blower
- Soldering gun
- Tweezers
- Flux
- Solder



Page 4 of 12

2. System Connector



Use soldering iron to remove defective component. Avoid excessive heat! Watch surrounding components! Re-solder new component afterwards.


E-commerce order number: C39334-Z97-C448 Soldering temperature: 240 – 255°C


IRIS Diagnose Code: 46100 Interface/ Charging Connector/ Mechanical Damage

47300 Interface/ Data Interface/ Mechanical Damage 4B100 Interface/ Headset Connector/ Mechanical Damage

Page 5 of 12

3. LED





LED

Use soldering iron to remove defective component. Avoid excessive heat! Watch surrounding components! Resolder new component afterwards. **Attention: Remove Metal Dome Sheet before!!!**

E-commerce order number: V20810-U6208-D670


Soldering temperature: 240 - 255°C

IRIS Diagnose Code: 36000 Keys/Illumination

Page 6 of 12

4. Battery Connector

	Customer:	GRT:
	Mobile does not switch on	No Support




Use hot air blower to remove defective component. Avoid excessive heat! Watch surrounding components!

E-commerce order number: C39334-Z97-C486 Soldering temperature: 240 – 255°C

IRIS Diagnose Code: 91500 Functionality / Switch Off Problems / Battery Contacts Damage

Page 7 of 12

5. Backup Battery



Backup Battery

Use hot air blower to remove defective component. Avoid excessive heat! Watch surrounding components! Re-solder new component afterwards.


E-commerce order number: V39328-F2705-Z2 Soldering temperature: 240 – 255°C

IRIS Diagnose Code: C8100 Settings/ General / Clock / Date

Page 8 of 12

6. Microphone

Customer: Customer parameter (date and time) are not saved	GRT: No Support
when battery is removed	



Microphone

Use hot air blower to remove defective component. Avoid excessive heat! Watch surrounding components!

E-commerce order number: C39254-Z6-C139 Soldering temperature: 240 – 255°C


IRIS Diagnose Code: 73110 Acoustics/ Transmitting / Microphone / No Function

73130 Acoustics/ Transmitting / Microphone / Mechanical damage

73140 Acoustics/ Transmitting / Microphone / Noise

7. Speaker Spring

Fault Symptoms		
Customer:	GRT:	
No ring tone under correct setting.	No Support	



Speaker Spring

Use tweezers to remove defective component. Avoid excessive heat! Watch surrounding components! Re-solder new component afterwards.

E-commerce order number: C39334-Z97-C487 Soldering temperature: 240 – 255°C


IRIS Diagnose Code: 74000 Acoustics/ Ringer / No Function

41300 Acoustics/ Ringer / Mechanical Damage

Page 10 of 12

8. IRDA

Fault Symptoms	
Customer:	GRT:
No infrared connection possible.	No Support



IRDA

Use hot air blower to remove defective component. Avoid excessive heat! Watch surrounding components! Re-solder new component afterwards.

E-commerce order number: V20810-U6208-D670


Soldering temperature: 240 – 255°C

IRIS Diagnose Code: 41100 Interfaces/ IRDA / No Function

41300 Interfaces/ IRDA / Mechanical Damage

9. Hall IC

Fault Symptoms		
Customer:	GRT:	
No infrared connection possible.	No Support	



Hall IC

Use hot air blower to remove defective component. Avoid excessive heat! Watch surrounding components! Re-solder new component afterwards.

E-commerce order number: V20810-U6207-D670

Soldering temperature: 240 – 255°C

IRIS Diagnose Code: