

# Level 2.5 Repair Documentation for XELIBRI

## X2 & X4



Issue	Date	Author	Description
0.9	15.04.03	Noblet	First release
1.0	22.05.03	Lerner	Layout update and 1 <sup>st</sup> official release

V 1.0	Page 1 of 14	ICM MP CCQ GRM
X2 / X4	Company Confidential Copyright 2003© Siemens AG	04/03

**Table of Contents:**

<b>1 XELIBRI Level2.5 Repair Location Code.....</b>	<b>4</b>
<b>2 BATTERY CONNECTOR.....</b>	<b>5</b>
<b>    2.1 Affected Units.....</b>	<b>5</b>
2.1.1 Type: Xelibri .....	5
2.1.2. Affected IMEIs/Date Codes: All/All.....	5
2.1.3. Affected SW-versions: All .....	5
2.1.4 Fault Code for LSO reporting: NA.....	5
<b>    2.2 Fault Description .....</b>	<b>5</b>
2.2.1 Fault Symptoms for customers:.....	5
2.2.2 Fault Symptom on GSM tester:.....	5
2.2.3 Component Information .....	5
<b>    2.3. Priority: .....</b>	<b>6</b>
<b>    2.4. Repair document.....</b>	<b>6</b>
2.4.1 Description of procedure.....	6
2.4.1.1. Diagnosis.....	6
2.4.1.2. Repair by component change .....	6
2.4.1.3 Repair by SW-booting.....	6
2.4.1.4 Test.....	6
2.4.2 List of material .....	6
2.4.2.1 Components.....	6
2.4.2.2 Jigs and Tools.....	6
2.4.2.3 Special tools .....	7
2.4.2.4 Working materials.....	7
2.4.3 Drawing.....	7
<b>3 I/O CONNECTOR.....</b>	<b>8</b>
<b>    3.1 Affected Units.....</b>	<b>8</b>
3.1.1 Type: Xelibri .....	8
3.1.2 Affected IMEIs/Date Codes: All/All.....	8
3.1.3 Affected SW-versions: All .....	8
3.1.4 Fault Code for LSO reporting: NA.....	8
<b>    3.2 Fault Description.....</b>	<b>8</b>
3.2.1 Fault Symptoms for customers:.....	8
3.2.2 Fault Symptom on GSM tester:.....	8
3.2.3 Component Information .....	8
<b>    3.3 Priority:.....</b>	<b>9</b>
<b>    3.4 Repair document.....</b>	<b>9</b>
3.4.1 Description of procedure .....	9
3.4.1.1 Diagnosis.....	9
3.4.1.2 Repair by component change .....	9
3.4.1.3 Repair by SW-booting.....	9
3.4.1.4 Test.....	9
3.4.2 List of material .....	9
3.4.2.1 Components.....	9
3.4.3 Jigs and Tools.....	10
3.4.4 Special tools .....	10
3.4.5 Working materials.....	10
3.4.6 Drawing.....	10


V 1.0	Page 2 of 14	ICM MP CCQ GRM
X2 / X4	Company Confidential Copyright 2003© Siemens AG	04/03

<b>4 Other SMT components.....</b>	<b>11</b>
<b>4.1 Affected Units.....</b>	<b>11</b>
4.1.1 Type: Xelibri .....	11
4.1.2 Affected IMEIs/Date Codes: All/All.....	11
4.1.3 Affected SW-versions: All .....	11
4.1.4 Fault Code for LSO reporting: NA.....	11
<b>4.2 Fault Description.....</b>	<b>11</b>
4.2.1 Fault Symptoms for customers:.....	11
4.2.2 Fault Symptom on GSM tester:.....	11
4.2.3 Component Information .....	11
<b>4.3 Priority:.....</b>	<b>12</b>
<b>4.4 Repair document.....</b>	<b>12</b>
4.4.1 Description of procedure .....	12
4.4.1.1 Diagnosis.....	12
4.4.1.2 Repair by component change .....	12
4.4.1.3 Repair by SW-booting.....	12
4.4.1.4 Test.....	12
4.4.2 List of material .....	12
4.4.2.1 Components.....	12
4.4.2.2 Jigs and Tools.....	12
4.4.3 Special tools .....	13
4.4.4 Working materials.....	13
4.4.5 Drawing.....	13
<b>5 TEST POINTS LOCATION.....</b>	<b>13</b>
<b>6 PCB OVERVIEW .....</b>	<b>14</b>

V 1.0	Page 3 of 14	ICM MP CCQ GRM
X2 / X4	Company Confidential Copyright 2003© Siemens AG	04/03

## 1 XELIBRI Level2.5 Repair Location Code

Single side product



V 1.0	Page 4 of 14	ICM MP CCQ GRM
X2 / X4	Company Confidential Copyright 2003© Siemens AG	04/03

## 2 BATTERY CONNECTOR

### 2.1 Affected Units

- 2.1.1 Type:** Xelibri  
**2.1.2 Affected IMEIs/Date Codes:** All/All  
**2.1.3 Affected SW-versions:** All  
**2.1.4 Fault Code for LSO reporting:** NA

### 2.2 Fault Description

#### 2.2.1 Fault Symptoms for customers:


Can't power on under normal operation  
Can't charge this handset when power off

#### 2.2.2 Fault Symptom on GSM tester:

This fault can not be detected with a GSM-Tester

#### 2.2.3 Component Information

The connector (1610) is the battery connector with 3 contacts.  
During power on, 3.5V to 4.2V is supplied to the handset via VBat.  
VERROR is provided to the Battery, goes into the Power Management Unit control charge.



V 1.0	Page 5 of 14	ICM MP CCQ GRM
X2 / X4	Company Confidential Copyright 2003© Siemens AG	04/03

## 2.3. Priority:

- .....Mandatory
- .....Repair
- .....Optional
- .....Not Yet Defined

## 2.4. Repair document

### 2.4.1 Description of procedure

#### 2.4.1.1 Diagnosis

Visually check pins for oxidation or deformity.

Measure pins to test points (Vbat, GND, Verror) with a multimeter to check for continuity.

#### 2.4.1.2 Repair by component change

1. Use a hot air nozzle to remove the defective connector.

***Do not apply excessive heat and flow to avoid to destroy the adjoining solder joints.***

2. Level the solder joint on the pads (eventually add solder).
3. Secure new connector on the PCBA.
4. Reheat the solder on the pads with a fine-tipped soldering iron to allow the solder to flow on the connector's pins.

#### 2.4.1.3 Repair by SW-booting

Not possible !

#### 2.4.1.4 Test

Switch on the handset after repair

### 2.4.2 List of material

#### 2.4.2.1 Components

Battery connector

Part-Number: Not yet defined !

#### 2.4.2.2 Jigs and Tools

V 1.0	Page 6 of 14	ICM MP CCQ GRM
X2 / X4	Company Confidential Copyright 2003© Siemens AG	04/03

Hot air Blower  
Soldering Iron


#### 2.4.2.3 Special tools

Multimeter

#### 2.4.2.4 Working materials

Solder wire

### 2.4.3 Drawing



**Figure 1: XELIBRI Board Battery Connector Placement**

V 1.0	Page 7 of 14	ICM MP CCQ GRM
X2 / X4	Company Confidential Copyright 2003© Siemens AG	04/03

## 3 I/O CONNECTOR

### 3.1 Affected Units

- 3.1.1 Type: Xelibri  
3.1.2 Affected IMEIs/Date Codes: All/All  
3.1.3 Affected SW-versions: All  
3.1.4 Fault Code for LSO reporting: NA

### 3.2 Fault Description

#### 3.2.1 Fault Symptoms for customers:


Can not charge the handset

#### 3.2.2 Fault Symptom on GSM tester:

This fault can not be detected with a GSM-Tester

#### 3.2.3 Component Information

The connector (1660) is I/O connector (12 contacts) used the adapter charger.  
The adapter charger uses the PIN1 for V\_EXTERNAL\_Charge and PIN2 GND BOTTOM



V 1.0	Page 8 of 14	ICM MP CCQ GRM
X2 / X4	Company Confidential Copyright 2003© Siemens AG	04/03

### 3.3 Priority:

- .....Mandatory
- .....Repair
- .....Optional
- .....Not Yet Defined

### 3.4 Repair document

#### 3.4.1 Description of procedure

##### 3.4.1.1 Diagnosis

Visually check pins for oxidation or deformity.

Visual inspection of the fittings and I/O pads solder joints (short circuit, leak, poor brightness).

Measure pins to test points (Vexternal charge, GND) with a multimeter to check for continuity

##### 3.4.1.2 Repair by component change

1. Use a hot air nozzle to remove the defective connector.

*Do not apply excessive heat and flow to avoid to destroy the adjoining solder joints.*

2. Level the solder joint on the pads (eventually add solder).
3. Secure new connector on the PCBA.
4. Reheat the solder on the pads with a fine-tipped soldering iron to allow the solder to flow on th the connector's pins.

##### 3.4.1.3 Repair by SW-booting

Not possible!

##### 3.4.1.4 Test

Plug the adapter charger and check if there is a signal on test point F611 (V\_EXT\_CHARGE)

#### 3.4.2 List of material

##### 3.4.2.1 Components

I/O connector

Part-Number: Not yet defined !

V 1.0	Page 9 of 14	ICM MP CCQ GRM
X2 / X4	Company Confidential Copyright 2003© Siemens AG	04/03

**3.4.3 Jigs and Tools**


Hot air Blower  
Soldering Iron

**3.4.4 Special tools**

Multimeter

**3.4.5 Working materials**

Solder wire

**3.4.6 Drawing**

**Figure 2: XELIBRI Board Battery Connector Placement**

V 1.0	<b>Page 10 of 14</b>  <b>Company Confidential</b> Copyright 2003© Siemens AG	ICM MP CCQ GRM  04/03
X2 / X4		

## 4 Other SMT components

### 4.1 Affected Units

- 4.1.1 **Type:** Xelibri  
4.1.2 **Affected IMEIs/Date Codes:** All/All  
4.1.3 **Affected SW-versions:** All  
4.1.4 **Fault Code for LSO reporting:** NA

### 4.2 Fault Description

#### 4.2.1 Fault Symptoms for customers:

Normaly no special complain from customer. Desoldered or damaged components during a connector rework.

#### 4.2.2 Fault Symptom on GSM tester:

This fault can not be detected with a GSM-Tester

#### 4.2.3 Component Information

Position	Component Type	Order No.	Value / Labelling
2012	Capacitor	Not defined yet	TAJA226K010S
7600	Charge Chip	Not defined yet	ST3S01PHD-TR
3632	Resistor	Not defined yet	RL1206JR-070R24
3642	Resistor	Not defined yet	RC0402JR-07330K
3643	Resistor	Not defined yet	RC0402JR-07220K
3655	Resistor	Not defined yet	RC0402JR-07330K
3656	Resistor	Not defined yet	RC0402JR-07220K
3540	Resistor	Not defined yet	RC0402JR-07120R
6630	Diode	Not defined yet	BZD27-C15

V 1.0	Page 11 of 14	ICM MP CCQ GRM
X2 / X4	Company Confidential Copyright 2003© Siemens AG	04/03

### 4.3 Priority:

- .....Mandatory
- .....Repair
- .....Optional
- .....Not Yet Defined

### 4.4 Repair document

#### 4.4.1 Description of procedure

##### 4.4.1.1 Diagnosis

Visual inspection of the solder joints (bad soldering, poor brightness, no joint, bad placement, no component).

##### 4.4.1.2 Repair by component change

1. Use a hot air nozzle to remove the charge chip (pos. 7600) and the zener diode (pos. 6630) and a fine-tipped soldering iron for the other components.
2. Level the solder joint on the pads (eventually add solder).
3. Replace a new component on the pads.
4. Reheat the solder on the pads with a fine-tipped soldering iron to allow the solder to flow on the contacts (eventually add solder with a solder wire).

##### 4.4.1.3 Repair by SW-booting

Not possible!

##### 4.4.1.4 Test

Measure the electrical value by applying a multimeter on the pads.  
Or the charge chip, plug the charger and check the stroke running on the LCD.

#### 4.4.2 List of material

##### 4.4.2.1 Components

See above.

##### 4.4.2.2 Jigs and Tools

Hot air Blower  
Soldering Iron

V 1.0	Page 12 of 14	ICM MP CCQ GRM
X2 / X4	Company Confidential Copyright 2003© Siemens AG	04/03

#### 4.4.3 Special tools

Multimeter


#### 4.4.4 Working materials

Solder wire

#### 4.4.5 Drawing


See chapter 6. PCB overview.

## 5 TEST POINTS LOCATION



V 1.0	Page 13 of 14	ICM MP CCQ GRM
X2 / X4	Company Confidential Copyright 2003© Siemens AG	04/03

6 PCB OVERVIEW



V 1.0	Page 14 of 14	ICM MP CCQ GRM
X2 / X4	Company Confidential Copyright 2003© Siemens AG	01/03