




Date: 2015-10-27

B2X Service Repair Information:	Reboot issue displaying “optimizing apps”
Info ID:	SRI-EMEA-2015-13_rev2
Countries:	EMEA
Carrier:	-
Repair Level:	L2
Affected Models:	xPlay / Nexus6 / XT1100

Problem

This process document will give instruction of Nexus6 flashing process when customer devices returned for repair with a reboot issue by optimizing apps displayed in the phone.



Solution

MASC have to perform board swap !

With kind regards

B2X Service support team

