

Middle East & North Africa Personal Communication Sector

Field Service Information

C550 Display Missing Segment

Our Reference:	SI27_3_2004
Date:	March 31, 2003
Pages (including this page):	2

Prepared by:

Mohamed Morsy Customer Services Manager, Middle East & North Africa



MOTOROLA

Middle East & North Africa

Date: March 31, 2003

Our Reference: SI27_3_2004

Product/System: C550

Subject: C550 Display Missing Segment

FIELD SERVICE INFORMATION

Problem:

An issue has been identified during the 2nd 200 NPI analysis of C550 in PRC.

The root cause is ITO corrosion.

Solution:

LCD supplier Philips has implemented new SOP tightly to reduce the risk of contamination from Week09, 2004.

- 1. Initiate SOP of finishing cell handling instruction to define handling method in order to reduce the risk of contamination caused by improper handling.
- 2. Update SOP of finishing cleaning procedure to add regularly cleaning of ACF cutter of COG bonder.

Field Service Action:

Any C550 returns of LCD Missing Segment should be should replace a new LCD module.

Service Entry Code:

M-Claim Code NA Service Entry Code:

Customer Complaint:	DIM02
Problem Found:	DIM02
Reference Designator:	DIS
Repair:	RPT01

Display Main - Missing Pixels / Icons Display Main - Missing Pixels / Icons Display Replace Part - Defective