

FIELD SERVICE BULLETIN

FSB Number: LVCCFSB2005-309
Authors: Darwin Garcia
Date: October 13, 2005
Total No. of Pages: 2
Subject: **V3 Flip Water Detect Labels**
Model Affected: **V3**
Level of Repair: 2

Problem

Service is aware that service centers have raised concerns about detecting water damage in the flip assembly.

Solution

Placement of two 3mm water detect labels in the V3 flip assembly was implemented at the factories on week 40.



Two water detect labels to be placed as shown

These are NOT the same labels found on the PCB board and in the battery compartment.



Consumer Solutions & Support
US Competency Center
600 North US Highway 45
Libertyville, Illinois 60048
Website: gs.mot.com

Field Service Action

Customer Returns:

Add the two 3mm water detect labels in repairs that required removal on the flip assembly.

Part Number: 5471536C01 (They are supplied by Fabritech)

Call Center Action:

N/A

Service Inventory

Place new order for 3mm water detect labels.

Global Codes

M Claims:

Customer Complaint Codes: N/A

Problem Found Code: N/A

Repair Code: RPM11 (Replace Mechanical Part - Refurbishment)