




MOTOROLA UK
 REDWOOD
 CROCKFORD LANE
 CHINEHAM BUSINESS PARK
 CHINEHAM
 BASINGSTOKE
 UNITED KINGDOM RG24 8WQ

CSB-1007-2
 Country : UK
 Date : 10/4/2006
 APC : E23
 Repair Level : 2

Title V3V3 05 CR - GSM - RAZR Label for Factory Rework Flip
 Model Effected V3 & V3_05

PROBLEM

Service has being made aware that the factory changed the RAZR's flip assembly label color from white to yellow for only rework flips to improve traceability.



Note: The flip assembly label is only visible after disassembly of the rear housing.

SOLUTION

N/A

FIELD SERVICE ACTION

Service awareness.

CALL CENTER ACTION

N/A

SERVICE ENTRY CODE

Global Service Codes

Complaint Code:
 Problem Found Code:

Reference Designator:

Repair Code:

If applicable, note this bulletin number on warranty claim forms and make necessary changes to service manuals.2006-356
© Copyright 2006 Motorola Inc. All Rights Reserved.

[Close](#) | [Print](#)