

# Technical Bulletin

**Bulletin No: 1005**  
**Issue Date: 20/06/2003**  
**Product: GX10**

## Main Fuse Change (FS301)

Fuse FS301 has been changed in the manufacturing process. The modified fuse is more resilient to the initial current surge and will reduce the occurrence of the fuse blowing during normal operation.

The old fuse, Part Number QFS-L1036YCZZN should no longer be used, the new fuse Part Number QFS-L252EAFNZN must be used instead.

It is not necessary to replace the fuse unless it is found to be faulty.

