

Technical Bulletin

Bulletin No: 1010
Issue Date: 23/09/2003
Product: GX10 / GX10i

CMD55 Test set Issue

RF tuning of GX10 / GX10i products using a CMD55 test set is causing the IMEI of the phone to be corrupted and rewritten with the factory default IMEI of 004400295655630.

The CMD55 test set **should not** be used for RF tuning with either the GX10 / GX10i until further notice.

Should a GX10 / GX10i require RF tuning and no other suitable test set other than a CMD55 is available then the PCB should be replaced and the failed PCB quarantined.