


⊕	EARN
⊕	EARP

GSM SERVICE SUPPORT	2004.7.12
Level 3 Signal Flow	Rev.1.0
C115	Rev.1.0
TC Chen	Page 1 of 2

			LEDKEY_EN	VBACKUP	VRIO_2.8V	CLK32K_OUT			
--	--	--	-----------	---------	-----------	------------	--	--	--



			MICBIAS	HSMICBIAS	VRMEM_2.8V	VRRAM_2.8V	CLK13M_OUT	DLPWR		
--	--	--	---------	-----------	------------	------------	------------	-------	--	--

⊕	EARP
⊖	EARN
⊕	BUZZER
⊖	HSD
⊕	VIBRATOR
⊖	HSMICIP
⊕	MICIP
⊖	MICIN
⊕	RXI
⊖	RXQ

GSM SERVICE SUPPORT	2004.7.12
Level 3 Signal Flow	Rev.1.0
C115	Rev.1.0
TC Chen	Page 2 of 2