


**Note :**  
**This drawing refers only to the first PCB-Version of the product !**

**REVISIONS**

GSM SERVICE SUPPORT GROUP	2001.11.07
Level 3 Board Layout	Rev. 1.0
TriBand V.101 (Camelot)	84D86470K01_P9
Michael Hansen, Ralf Lorenzen-Scheil, Ray Collins	Page 4 of 4

# TriBand V.101 (Camelot) 84D86470K01\_P9


GSM Service Support  
Level 3 Authorized



**Note :**  
This drawing refers only to the first PCB-Version of the product !

## REVISIONS

GSM SERVICE SUPPORT GROUP	2001.11.07
Level 3 Board Layout	Rev. 1.0
TriBand V.101 (Camelot)	84D86470K01_P9
Michael Hansen, Ralf Lorenzen-Scheil, Ray Collins	Page 3 of 4




LAYER 1 (TOP SIDE)

**Note :**  
**This drawing refers only to the first PCB-Version of the product !**

**REVISIONS**

GSM SERVICE SUPPORT GROUP	2001.11.07
Level 3 Board Layout	Rev. 1.0
TriBand V.101 (Camelot)	84D86470K01_P9
Michael Hansen, Ralf Lorenzen-Scheil, Ray Collins	Page 2 of 4



LAYER 6 (BOTTOM SIDE)

**Note :**  
This drawing refers only to the first PCB-Version of the product !

**REVISIONS**

GSM SERVICE SUPPORT GROUP	2001.11.07
Level 3 Board Layout	Rev. 1.0
TriBand V.101 (Camelot)	84D86470K01_P9
Michael Hansen, Ralf Lorenzen-Scheil, Ray Collins	Page 1 of 4