




VBACKUP    VRIO\_2.8    CLK32K\_OUT    LEDB    PAENA    APC    GSM\_TXEN    VC2    VC1    TRENA



DLPWR    VRMEM\_2.8V    VRRAM\_2.8V    CLK13M\_OUT    MICBIAS    26MHz    AFC

Ⓒ	EARP	Ⓛ	MICIP		
Ⓓ	EARN	Ⓜ	MICIN		
Ⓕ	HSO	Ⓨ	RXI		
Ⓖ	VIBRATOR	Ⓩ	RXQ	Ⓟ	HSMICIP

V171

Service Engineering & Optimization  
Level 3 Authorized

REVISIONS	
Service Engineering & Optimization	2004.10.12
Level 3 Signal Flow	Rev. 1.0
V171 EU	
Alexander Buehler, Michael Mauderer	Page 2 of 2