



REVISIONS		
Service Engineering & Optimization	Level 3 Board Layout	2004.11.04
MPX - Main PCB Top	Alexander Buchler, Michael Mauderer	Rev. 1.0
		PM-0145-06
		Page 1 of 4

MPX PM-0145-06



REVISIONS


Revision	Description	Date
001	Service Engineering & Optimization	2004.11.04
002	Level 3 Board Layout	Rev. 1.0
003	MPX - Main PCB BOT	PM-0145-06
004	Alexander Buehler, Michael Mauderer	Page 2 of 4



REVISIONS

Service Engineering & Optimization	2004.11.04
Level 3 Board Layout	Rev. 1.0
MPX - LCM PCB Top	PM-0145-06
Alexander Buehler, Michael Mauderer	Page 3 of 4





REVISIONS

Service Engineering & Optimization	2004.11.04
Level 3 Board Layout	Rev. 1.0
MPX - LCM PCB BOT	PM-0145-06
Alexander Buehler, Michael Mauderer	Page 4 of 4