

Technical Bulletin

Bulletin No: 1014
Issue Date: 15/10/2003
Product: GX10

Master Reset after Software Upgrade

A Master Reset of the GX10 Handset **MUST** be performed following a Software Upgrade from version A0256 to A0304, A0305 or A0308.

If the Handset Code is unknown, use PWDinit.exe within the GX10 SPST to reset the Handset Code to '0000'.