

Mobile Phone: GX10 (TQ-GX10)

Date: 03/12/2003

No.: TB1016

Technical Report

Title

Relay FPC-A and FPC-B

Model

GX10 (TQ-GX10)

General

Relay FPC-A and FPC-B of GX10 have been unified into GX10i's parts in order to improve productivity.

Parts information

П	REF. NO.	PARTS NAME	PARTS CODE OF REPLACEMENT PARTS				Inter-	Effective	Price Rank for
E M			CURRENT	Q'ty	NEW	Q'ty	change- ability	from	new parts
1	104-25	FPC-A	RUNTK0695AFZZ	1	RUNTK0725AFZZ	1	Α	June '03	AY
2	104-26	FPC-B	RUNTK0671AFZZ	1	RUNTK0726AFZZ	1	Α	June '03	AX

<interchangeability></interchangeability>					
A: Interchangeable.	D: Not interchangeable.				
B: Current type can be used in place of new type.	E: Others.				
New type cannot be used in place of current type.					
C: Current type cannot be used in place of new type.					
New type can be used in place of current type.					

Field action (in Repair centre)

Please use new parts after running out of the current parts.

No need to replace both FPC-A and FPC-B together.

It is possible to combine current parts (FPC-A or FPC-B) with new parts (FPC-A or FPC-B).