



REVISIONS	
Service Engineering & Optimization	2004.10.11
Level 3 Board Layout	Rev. 1.0
A 668	
Alexander Buchler, Michael Hansen	Page 1 of 4



REVISIONS	
Service Engineering & Optimization	2004.10.11
Level 3 Board Layout	Rev. 1.0
A 668	
Alexander Buehler, Michael Hansen	Page 3 of 4



REVISIONS

Service Engineering & Optimization	2004.10.11
Level 3 Board Layout	Rev. L0
A 668	
Alexander Buehler, Michael Hansen	Page 4 of 4