


GSM SERVICE SUPPORT GROUP	2004.09.05
Block Diagram	Rev. 1.2
MPX220	
Alex Buehler, Michael Mauderer	Page 2 of 3



GSM SERVICESUPPORT GROUP	2004.09.05
Block Diagram	Rev. 1.2
MPX220	
Alex Buehler, Michael Mauderer	Page3of 3