FIELD SERVICE BULLETIN

FSB Number Author Date Subject Model Affected Level Of Repairs BJCCFSB2008 - 89 hong fang Wednesday, March 19, 2008 **GSM - W230 - No screen saver** w230 1

Problem

Service is aware of an issue, some user complained that the screensaver function can't be active if the screensaver is set.

Solution

This issue isn't the phone problem.

If the auto keypad lock was set, then screensaver feature would be disable. This can save battery life.

If the auto keypad lock was off mode, the screensaver feature would be enable.

Auto keypad lock setting procedure:

Mean---Settings----Security---Auto key lock---Off

Field Service Action

W230 phone returned to service center with the complaint of 'No screensaver function'. Please educate the user how to do the settings as above procedure.

Service Inventory

N/A

Call Center Action

When a customer contacts the Motorola call center, with the complaint of 'No Screensaver Function'. Please communicate the customer that the Auto key lock feature of the phone need set to Off mode. If Auto key lock feature was set, the Screensaver function would be disable.

© Copyright 2006 Motorola Inc. All Rights Reserved Page 1 of 2of Motorola Field Service Bulletin Number - BJCCFSB2008 - 89 Motorola Internal Use Only

Service Entry Code

Global Service Codes Complaint Code: FTR06 - Feature - MMS screensaver

Problem Found Code: FTR06 - Feature - MMS screensaver

Reference Designator:

Repair Code: RTU01 - Return Unrepaired - Tested and passed specs

Asia Service Codes Complaint Code: Problem Found Code: Reference Designator Repair Code: